10/20/21, 7:31 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG21006085/KRA3Q2

Date:

20/10/2021

REFERENCE

Date of Loss:

Reg. Date:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

2100304099 SKF5837H

Odometer:

Claimant Vehicle No:

SMN4908C 11/05/2021

Insured Vehicle No: Nature of Claim:

TP

Claim No:

2212846523SG

K9KF649D060018

102202 km

VF1RFA00562894875

Yes

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMN4908C

Make & Model: RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A)

Engine No: 14/08/2019 (Man. Year: 2019) Chassis No:

Colour: Metallic Beige

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Engine Modification: Handbrake (Serviceable): Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size: 195/55 R20 195/55 R20 Front Left Side: Goodyear 9 mm Rear Left Side: Goodyear 9 mm Front Right Side: Goodyear 9 mm Rear Right Side: Goodyear 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,235.05	1,079.66	3,155.39	74.51
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,200.00	650.00	1,550.00	70.45
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,435.05	1,729.66	4,705.39	73.12
	Approved Total (Overridden) (S\$)		1,350.00		

(S\$)	6,435.05	1,350.00	5,085.05	79.02
+ GST 7.00/7.00% (S\$)	450.45	94.50	355.95	79.02
Nett Amount (S\$)	6,885.50	1,444.50	5,441.00	79.02
+ Car Rental (4.0)	x S\$92.00/day) (S\$)	368.00		
+ D	oc/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	1,814.50		

INSPECTION

Date of Assignment: 24/05/2021

Munich Autocare Pte Ltd (HQ) Date Inspected: Inspected At: 60 Jalan Lam Huat, #06-43 24/05/2021

Singapore 737869

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other circumstances is hereby expressly

REPAIR DETAILS

Recommended Parts

	Condition	Repairer's	Amount
*REAR BUMPER ASSY	Dented / Cut	1,152.96 FL	*1,152.96 FL
*REAR LOWER BUMPER	Serviceable	492.78 FL	*- FL
*REAR LOWER BUMPER SILVER MOULDING	No such part	696.24 FL	*- FL
*REVERSE SENSOR	Serviceable	510.72 FL	*- FL
*REAR BUMPER RETAINER RH	Serviceable	288.96 FL	*- FL
*REAR BUMPER RETAINER LH	Serviceable	288.96 FL	*- FL
*REAR BUMPER BRACKET CENTRE	Serviceable	357.84 FL	*- FL
*RIVET ALUMINIUM	Serviceable	42.00 FL	*- FL
*RIVET	Serviceable	55.44 FL	*- FL
*REAR BUMPER REINFORCEMENT	Serviceable	685.68 FL	*- FL
*REAR BUMPER PAD SUPPORT BRACKET	Serviceable	87.36 FL	*- FL
*REAR BUMPER CLIPS	Necessary	42.00 FS	*42.00 FS
ListItemDisc.			
	Sub Total (S\$)	4,700.94	1,194.96
	- List Item Discount on L Items 10.00/10.00% (S\$)	465.89	115.30
	Total Parts (S\$)	4,235.05	1,079.66
	*REAR LOWER BUMPER *REAR LOWER BUMPER SILVER MOULDING *REVERSE SENSOR *REAR BUMPER RETAINER RH *REAR BUMPER RETAINER LH *REAR BUMPER BRACKET CENTRE *RIVET ALUMINIUM *RIVET *REAR BUMPER REINFORCEMENT *REAR BUMPER PAD SUPPORT BRACKET *REAR BUMPER CLIPS	*REAR LOWER BUMPER SILVER MOULDING *REVERSE SENSOR *REAR BUMPER RETAINER RH *REAR BUMPER RETAINER LH *REAR BUMPER BRACKET CENTRE *RIVET ALUMINIUM *REAR BUMPER REINFORCEMENT *REAR BUMPER PAD SUPPORT BRACKET *REAR BUMPER CLIPS Serviceable *REAR BUMPER CLIPS Sub Total (\$\$) - List Item Discount on L Items 10.00/10.00% (\$\$)	*REAR LOWER BUMPER *REAR LOWER BUMPER SILVER MOULDING *REVERSE SENSOR Serviceable 510.72 FL *REAR BUMPER RETAINER RH Serviceable 288.96 FL *REAR BUMPER RETAINER LH Serviceable 288.96 FL *REAR BUMPER BRACKET CENTRE Serviceable 357.84 FL *RIVET ALUMINIUM Serviceable 42.00 FL *RIVET Serviceable 55.44 FL *REAR BUMPER REINFORCEMENT Serviceable 55.44 FL *REAR BUMPER PAD SUPPORT BRACKET *REAR BUMPER CLIPS ListItem Disc. Sub Total (\$\$) 4,700.94 465.89

10/20/21, 7:31 PM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PANEL BEATING ,REALIGN REAR BUMPER ,TAILGATE AND ALL NECESSARY ETC	New	1,000.00	200.00
2	TO REMOVE & REFIX REVERSE SENSOR	New	250.00	50.00
3	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER ,TAILGATE AND ALL NECESSARY ETC	New	800.00	400.00
4	TO APPLY ANTI-TUFF COAT	New	150.00	0.00
		Gross Labour Cost (S\$)	2,200.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >