

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21006086/EUF3E2

Date: 27/07/2021

REFERENCE

Insured/Claimant:	HOON AIK SEONG	Policy No:	2100437532		
Date of Loss:	23/05/2021	Nature of Claim:	OD	Claim No:	6226294636SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW7691H	Engine No:	G4FGFH784982
Make & Model:	KIA FORTE K3, 1.6 (A)	Chassis No:	KNAFZ411MF5472112
Reg. Date:	16/11/2015 (Man. Year: 2015)	Odometer:	32485 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$45,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Firenza 4 mm	Rear Left Side:	Firenza 4 mm
Front Right Side:	Firenza 4 mm	Rear Right Side:	Firenza 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,280.80	1,145.60	1,135.20	49.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	2,280.00	1,190.00	34.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,750.80	3,425.60	2,325.20	40.43
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	5,150.80	2,825.60	2,325.20	45.14
+ GST 7.00/7.00% (S\$)	360.56	197.79	162.77	45.14
Nett Amount (S\$)	5,511.36	3,023.39	2,487.97	45.14

INSPECTION

Date of Assignment:	24/05/2021	
Date Inspected:	24/05/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*PANEL ASSY-REAR DOOR, RH	Dented	1,361.00 FL	*1,361.00 FL
3	1		*W/STRIP ASSY-RR DR BELT O/S RH	Not Necessary	89.00 FL	*- FL
4	1		*TAPE-RR DR FRAME BLACK RR, RH	Necessary	8.00 FL	*8.00 FL
5	1		*BLACK TAPE-RR DR FRAME UPR, RH	Necessary	11.00 FL	*11.00 FL
6	1		*FILM-ANTI CHIPPG RH	Necessary	27.00 FL	*27.00 FL
7	1		*HANDLE ASSY-DOOR OUTSIDE	Repair	58.00 FL	*- FL
8	1		*COVER-FR DR O/S HDL, PASSENGER	Not Necessary	22.00 FL	*- FL
9	1		*K3 TEMPTATION RED K3R	Repair	1,000.00 FS	*- FS
					Sub Total (\$\$)	2,596.001,427.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	315.20281.40
					Total Parts (\$\$)	2,280.801,145.60

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RHR DOOR PNL & RH ROCKER PNL BODY KIT. REPAIR RHR FENDER & RH ROCKER PNL	New	1,600.00	880.00
2	RESPRAY RHR DOOR, RHR FENDER, RH ROCKER PNL & RH ROCKER PNL BODY KIT	New	1,400.00	1,050.00
3	REMOVE & REFIT RHR DOOR COMPONENT	New	120.00	120.00
4	REMOVE & REFIT TRIM & REAR SEAT TO FACILITATE REPAIR	New	120.00	0.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	40.00
8	SUPPLY BODY PNL SEALANT	New	40.00	40.00
Gross Labour Cost (\$)			3,470.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >