

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006087/GPA3Q2**Date:** 09/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100510076
Claimant Vehicle No :	FR7889R	Insured Vehicle No :	SLP7122J
Date of Loss:	28/04/2021	Nature of Claim:	TP
		Claim No:	4595193523SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FR7889R	Engine No:	EX400GEA50144
Make & Model:	KAWASAKI EX400G, 399cc	Chassis No:	JKAEX400GGDA50144
Reg. Date:	14/08/2019 (Man. Year: 2019)	Odometer:	30986 km
Colour:	Green		
Engine Capacity:	399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	150/60 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,097.80	7,739.00	6,358.80	45.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	660.00	400.00	260.00	39.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,757.80	8,139.00	6,618.80	44.85
+ GST 7.00/7.00% (S\$)	1,033.05	569.73	463.32	44.85
Nett Amount (S\$)	15,790.85	8,708.73	7,082.12	44.85
+ Loss of Use (4.0 x S\$25.00/day) (S\$)		100.00		
Nett Liability (S\$)		8,808.73		
Global Sum Settlement (S\$)		8,800.00		

INSPECTION

Date of Assignment:	24/05/2021	
Date Inspected:	24/05/2021	Inspected At: Sin Boon Motor Co (HQ) 10 Admiralty Street, #01-10/11, Northlink Building Singapore 757695
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOP WINDSHIELD	Cut	275.00 FL	*128.00 FL
2	1		*L/H MIRROR	Cut	225.00 FL	*129.00 FL
3	1		*R/H MIRROR	Cut	225.00 FL	*129.00 FL
4	1		*TOP COWLING	Broken	975.00 FL	*190.00 FL
5	1		*L/H SIGNAL FENDER FRONT	Cut	80.00 FL	*80.00 FL
6	1		*L/H SIDE FENDER UPPER	Cut	630.00 FL	*630.00 FL
7	1		*L/H LOW COWLING	Cut	340.00 FL	*255.00 FL
8	1		*HEADLIGHT (LED)	Cracked	2,410.00 FL	*755.00 FL
9	1		*LAMPSTAY (BRACKET)	Bent	478.00 FL	*75.00 FL
10	1		*R/H SIGNAL FENDER	Deformed	82.00 FL	*82.00 FL
11	1		*R/H SIDE FENDER REAR	Repair	215.00 FL	*- FL
12	1		*R/H LOWER COWLING	Deformed	328.00 FL	*255.00 FL
13	1		*R/H HANDLE BAR	Bent	242.00 FL	*185.00 FL
14	1		*L/H FORK	Bent	1,440.00 FL	*880.00 FL
15	1		*R/H FORK	Bent	1,440.00 FL	*880.00 FL
16	1		*FORK LOWER BRACKET	Bent	605.00 FL	*605.00 FL
17	1		*FORK UPPER BRACKET	Bent	595.00 FL	*545.00 FL
18	1		*FUEL TANK (PETROL)	Dented	1,920.00 FL	*880.00 FL
19	1		*L/H TAIL FENDER	Cut	156.00 FL	*156.00 FL
20	1		*R/H TAIL FENDER	Cut	156.00 FL	*156.00 FL
21	1		*EXHAUST PROTECTOR (MUFFLER)	Cut	456.00 FL	*160.00 FL
22	1		*FRONT FENDER (MAGUARD)	Cracked	380.00 FL	*288.00 FL
23	1		*L/H FRAME SLIDER	Cut	80.00 FL	*40.00 FL
24	1		*R/H FRAME SLIDER	Cut	80.00 FL	*40.00 FL
25	1		*L/H HANDLE BAR END PLUG	Cut	80.00 FL	*35.00 FL
26	1		*FRONT RIM SHAFT	Bent	153.00 FL	*97.00 FL
27	1		*L/H FOOT REST FRONT	Not Necessary	136.00 FL	*- FL
28	1		*STEERING CONE BEARING	Necessary	210.00 FL	*82.78 FL
29	1		*FRONT RIM	Bent	1,250.00 FL	*850.00 FL
30	1		*FRONT NUMBER PLATE	Necessary	20.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,662.00	8,597.78
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,564.20	858.78
Total Parts (\$\$)	14,097.80	7,739.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	600.00	350.00
2	TOW	New	60.00	50.00
Gross Labour Cost (S\$)			660.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >