FR7889R

Inspection Photo: Description: The front fender cracked. \$ 288.00

Inspection Photo:	Description:	Price:
	LH Side Fender Upper – Damaged.	\$ 630.00

Inspection Photo:	Description:	Price:
Kawasaki	LH Handlebar End Plug - Damaged.	\$ 35.00
	LH Side Mirror – Damaged.	\$ 129.00

Inspection Photo:	Description:	Price:
	Top Windshield – Cracked.	\$ 128.00
	RH Side Mirror – Damaged.	\$ 129.00

Inspection Photo:	Description:	Price:
	Top Cowling - Cracked	\$ 190.00

Inspection Photo:	Description:	Price:
Tribates 18	LH Frame Slider - Damaged	\$ 40.00
	LH Tail Fender – Damaged.	\$ 156.00

Inspection Photo:	Description:	Price:
Sum Linear Linea	Fuel Tank - Dented	\$ 880.00

Inspection Photo:	Description:	Price:
	HEADLIGHT (LED) — Cracked.	\$ 755.00

Inspection Photo:	Description:	Price:
A A SA	RH Lower Cowling - Distorted	\$ 255.00

Inspection Photo:	Description:	Price:
	RH Signal Fender – Deformed.	\$ 82.00

Inspection Photo:	Description:	Price:
	The LH fork & RH fork – Bent. Pls refer to	
	the below dismantle photos. The	
	damage of fork caused unbalancing of	
	motorbike and non-repairable.	
The same of the sa		
RH Fork		
-/		





Inspection Photo:	Description:	Price:
	Fork Lower Bracket - Bent	\$ 605.00

Inspection Photo:	Description:	Price:
	Fork Upper Bracket - Bent	\$ 545.00

Inspection Photo:	Description:	Price:
	Front Rim – Surveyor who conducted inspection tested front rim and found that it is wobble.	\$ 850.00