

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006089/NPA3Q2
Date: 17/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800046750
Claimant Vehicle No :	SHC1629U	Insured Vehicle No :	SGT838L
Date of Loss:	22/05/2021	Nature of Claim:	TP
		Claim No:	8043888612SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1629U		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS062606
Reg. Date:	23/08/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU303563752
Colour:	Blue	Odometer:	590534 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 4 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,059.62	2,674.25	2,385.37	47.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,750.00	390.00	18.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,199.62	4,424.25	2,775.37	38.55
Approved Total (Overridden) (S\$)		3,550.00		

(S\$)	7,199.62	3,550.00	3,649.62	50.69
+ GST 7.00/7.00% (S\$)	503.97	248.50	255.47	50.69
Nett Amount (S\$)	7,703.59	3,798.50	3,905.09	50.69
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Car Rental (6.0 x S\$125.40/day) (S\$)		752.40		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,852.90		
Global Sum Settlement (S\$)		4,800.00		

INSPECTION

Date of Assignment: 24/05/2021

Date Inspected: 24/05/2021

Estimated Period of Repair: 4.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB ASSY FRT DOOR RH	Dented	1,264.00 FL	*1,264.00 FL
2	1		*FRT DOOR OUTER HANDLE RH	Serviceable	378.90 FL	*- FL
3	1		*PANEL SUB ASSY RR DOOR RH	Dented	1,258.30 FL	*1,258.30 FL
4	1		*RR DOOR HINGE UPPER	Serviceable	82.30 FL	*- FL
5	1		*RR DOOR HINGE LOWER	Serviceable	82.30 FL	*- FL
6	1		*RR DOOR CHECK	Serviceable	155.70 FL	*- FL
7	1		*RR DOOR RUBBER SEAL OUTER RH	Serviceable	176.60 FL	*- FL
8	1		*MIRROR ASSY OUTER VIEW MIRROR RH	Serviceable	1,728.70 FL	*- FL
9	1		*ROCKER PANEL OUTER RH	Repair	576.00 FL	*- FL
10	1		*REAR FENDER RH	Dented	836.70 FL	*836.70 FL
11	1		*FRT DOOR COMFORT LOGO	Necessary	75.00 FS	*75.00 FS
12	1		*RR DOOR COMFORT & APP STICKER	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,694.50	3,514.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,634.88	839.75
Total Parts (\$\$)	5,059.62	2,674.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	700.00
2	SPRAY PAINTING CHARGE	New	1,000.00	900.00
3	WIRING CHARGE	New	50.00	0.00
4	TRANSFER OF FRT & RR DOOR	New	240.00	100.00
5	TUFF KOTE	New	50.00	50.00
Gross Labour Cost (S\$)			2,140.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >