

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III21003817/GTF3E2-1

Date: 16/06/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SLK593E **Insured Vehicle No :** SLS8247K
Date of Loss: 24/03/2021 Nature of Claim: TP Claim No: MFL2021D0001313

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK593E**
Make & Model: HONDA HR-V, 1.5 (A) Engine No: L15B4531361
Reg. Date: 04/01/2017 (Man. Year: 2016) Chassis No: JHMRU1810GX201361
Colour: Beige Odometer: 78958 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,693.96	4,091.48	4,602.48	52.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,320.00	1,540.00	1,780.00	53.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,013.96	5,631.48	6,382.48	53.13
Approved Total (Overridden) (S\$)		4,450.00		
Nett Amount (S\$)	12,013.96	4,450.00	7,563.96	62.96

INSPECTION

Date of Assignment: 24/05/2021
Date Inspected: 25/03/2021 Inspected At: Tsa Transport (HQ)
1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki
Bukit
Singapore 417883
Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jun 2021)
Parts:	M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK593E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	953.30 FL	*953.30 FL
2	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	56.20 FL	*56.20 FL
3	2		*REAR TAILGATE DAMPER L/R	Not Necessary	360.00 FL	*- FL
4	2		*REAR TAILGATE HINGES L/R	Not Necessary	100.00 FL	*- FL
5	2		*REAR TAILGATE WINDSCREEN INNER SEAL	Not Necessary	100.00 FL	*- FL
6	2		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	100.00 FL	*100.00 FL
7	1		*REAR TAILGATE WIPER MOTOR	Not Necessary	315.90 FL	*- FL
8	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	220.00 FL	*- FL
9	1		*REAR TAILGATE OUTER GARNISH H LOGO EMBLEM	Not Necessary	25.00 FL	*- FL
10	1		*REAR TAILGATE OUTER LOCK SWITCH	Faulty	175.50 FL	*175.50 FL
11	2		*REAR TAILGATE NUMBER PLATE LAMP L/R	Not Necessary	51.60 FL	*- FL
12	2		*REAR TAILGATE REFLECTOR L/R	Cracked	529.20 FL	*529.20 FL
13	2		*REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R	Serviceable	77.00 FL	*- FL
14	1		*REAR TAILGATE INNER PULL GARNISH	Bent	27.50 FL	*27.50 FL
15	1		*REAR TAILGATE INNER TRIM GARNISH	Cracked	153.40 FL	*153.40 FL
16	1		*REAR TAILGATE MECHANISM LOCK	Bent	180.00 FL	*180.00 FL
17	1		*REAR TAILGATE MECHANISM LOCK STRIKER	Serviceable	27.50 FL	*- FL
18	2		*REAR TAILGATE RUBBER GUIDE STOPPER L/R	Serviceable	37.00 FL	*- FL
19	1		*REAR TAILGATE WEATHER STRIP	Cut	96.80 FL	*96.80 FL
20	2		*REAR TAILLAMP L/R	Cracked	857.40 FL	*857.40 FL
21	2		*REAR FENDER INNER TRIM GARNISH L/R	Repair	590.00 FL	*- FL
22	1		*REAR BUMPER	Cracked	762.70 FL	*565.00 FL
23	2		*REAR BUMPER REFLECTOR L/R	Necessary	282.20 FL	*282.20 FL
24	4		*REAR BUMPER REVERSE SENSOR	Faulty	536.00 FS	*250.00 FS
25	2		*REAR BUMPER SIDE L/R	Cracked	390.00 FL	*390.00 FL
26	2		*REAR BUMPER SIDE RETAINER L/R	Bent	46.00 FL	*46.00 FL
27	2		*REAR FENDER ARCH GARNISH L/R	Not Necessary	390.00 FL	*- FL
28	1		*REAR FLOOR PANEL INNER TOP BOARD COVER	Repair	430.30 FL	*- FL
29	1		*REAR FLOOR PANEL COMPARTMENT TRAY SPONGE	Repair	485.30 FL	*- FL
30	1		*REAR END PANEL ANTENNA SENSOR	Faulty	60.10 FL	*60.10 FL
31	1		*REAR END PANEL BUZZLE SENSOR	Not Necessary	85.20 FL	*- FL
32	1		*REAR END PANEL INNER TOP GARNISH	Cracked	98.00 FL	*98.00 FL
33	1		*REAR END PANEL	Repair	415.60 FL	*- FL
34	1		*SET REAR TAILGATE INNER TRIM GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
35	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Necessary	40.00 FS	*15.00 FS
36	1		*REAR TAILGATE REVERSE CAMERA	Serviceable	800.00 FS	*- FS
37	1		*SET REAR TAILGATE SPOILER CLIPS	Necessary	40.00 FS	*15.00 FS
38	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*50.00 FS
39	1		*REAR TAILGATE NUMBER PLATE	Not Necessary	25.00 FS	*- FS
40	1		*REAR TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
41	2		*SET REAR TAILLAMP CLIPS L/R	Serviceable	80.00 FS	*- FS
42	2		*SET REAR FENDER ARCH GARNISH CLIPS L/R	Necessary	100.00 FS	*30.00 FS
43	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*40.00 FS
44	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	40.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,389.70 5,005.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	120.00	30.00
2	TO REMOVE, REINSTALL TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET	New	100.00	50.00
3	TO REMOVE, REINSTALL TAILGATE WINDSCREEN	New	180.00	120.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	700.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,600.00	600.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	40.00
Gross Labour Cost (\$\$)			3,320.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >