



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FY 3147M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	FORK INNER TUBES (CONSISTENT)	BENT / TWISTED	320.00	320.00
2	FORK OUTER TUBES (CONSISTENT)	BENT / TWISTED	340.00	340.00
1	FORK UNDER BRACKET (CONSISTENT)	BENT	175.00	125.00
1	FRONT RIM SHAFT (CONSISTENT)	CUT	42.00	42.00
1	FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	185.00	-
1	FRONT SPORT RIM (CONSISTENT)	BENT / WARPED	280.00	250.00
1	SET FRONT RIM SPOCKY (CONSISTENT)	NECESSARY	220.00	150.00
1	LAMPSTAY (CONSISTENT)	BENT	120.00	120.00
1	SIDE MIRRORS (CONSISTENT)	MISSING	80.00	80.00
1	HANDLE-BAR N/S (CONSISTENT)	BENT	100.00	100.00
1	HANDLE-BAR END (CONSISTENT)	CUT	36.00	25.00
1	CLUTCH LEVER (CONSISTENT)	SERVICEABLE	42.00	-
1	AIR INTAKE DUCT (CONSISTENT)	MISSING	95.00	45.00
1	FRONT FOOTREST N/S (CONSISTENT)	BROKEN	84.00	84.00
1	FRONT FOOTREST BRACKET (CONSISTENT)	CRACKED	130.00	130.00
1	GEAR PEDAL (CONSISTENT)	BENT	50.00	50.00
2	REAR FOOTREST (CONSISTENT)	N/S CUT	100.00	45.00
2	REAR FOOTREST BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	150.00	-
1	FUEL TANK (CONSISTENT)	TO REPAIR SEE LABOUR	480.00	-
2	REAR SIGNALS (CONSISTENT)	N/S BROKEN	84.00	42.00
1	REAR FENDER (CONSISTENT)	CRACKED	140.00	118.00
1	SET FAIRING ASSY (CONSISTENT)	BROKEN / CRACKED	1,050.00	850.00
	LESS 10% DISCOUNT		-430.30	-291.60
			3,872.70	2,624.40
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN) (CONSISTENT)	FRONT NECESSARY	28.00	10.00
2	FORK OILS (SN) (CONSISTENT)	NECESSARY	30.00	30.00
2	FORK OIL SEALS (SN) (CONSISTENT)	NECESSARY	56.00	56.00

Report Ref No. CS/ASM21006091/Uqce2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET STEERING CONE (SN) (CONSISTENT)	NECESSARY	85.00	60.00
			199.00	156.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.		50.00	50.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO RESPRAY PAINTING.		750.00	150.00
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF REAR FOOTREST BRACKET AND FUEL TANK.		450.00	300.00
			1,330.00	500.00
GRAND TOTAL			5,401.70	3,280.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CS/ASM21006091/Uqce2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.