

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006094/NRA3Q2
Date: 11/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100453972
Claimant Vehicle No :	SHC7668S	Insured Vehicle No :	SKE815J
Date of Loss:	22/05/2021	Nature of Claim:	TP
		Claim No:	5638807480SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC7668S		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEKU386575
Reg. Date:	14/11/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU183507
Colour:	Yellow	Odometer:	124717 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,471.76	367.12	2,104.64	85.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,410.00	1,940.00	470.00	19.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,881.76	2,307.12	2,574.64	52.74
+ GST 7.00/7.00% (S\$)	341.72	161.50	180.22	52.74

Nett Amount (S\$)	5,223.48	2,468.62	2,754.86	52.74
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Car Rental (6.0 x S\$125.19/day) (S\$)		751.14		
(S\$)		3,519.76		
Liabile Amount (50.00%) (S\$)		1,759.88		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,761.88		

INSPECTION

Date of Assignment: 24/05/2021

Date Inspected: 24/05/2021

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR OUTER MOULDING LH	Serviceable	125.30 FL	*- FL
2	1		*REAR LH DOOR PANEL	Repair	1,789.90 FL	*- FL
3	1		*REAR ROCKER GARNISH LH	Repair	715.60 FL	*- FL
4	1		*REAR WHEEL COVER LH	Scratched	346.40 FL	*346.40 FL
5	1		*PETROL STICKER	Necessary	10.00 FS	*10.00 FS
6	1		*REAR DOOR COMFORT APP STICKER	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,067.20	436.40
- List Item Discount on L Items 20.00/20.00% (\$)	595.44	69.28
Total Parts (\$)	2,471.76	367.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,050.00	1,050.00
2	SPRAY PAINTING CHARGE	New	1,000.00	850.00
3	REMOVE/REFIX DOOR PARTS	New	120.00	0.00
4	REMOVE/REFIX REAR UPHOLSTERY	New	90.00	0.00
5	TUFF COATING	New	90.00	40.00
6	CHECK WIRING	New	60.00	0.00
Gross Labour Cost (S\$)			2,410.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >