



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM21006097/Uba3q2 Date: 17/09/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2684C	Veh. Inspected	SJZ 3421T	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S1M03AKS	Excess (\$)	0.00	
Assign From		Assign Date	24/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA AIRWAVE (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	GJ11204465	Colour	BLACK	
Odometer	326948 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/45Z R16	WEST LAKE	6 mm	
L/H Front Tyre	205/45Z R16	WEST LAKE	6 mm	
R/H Rear Tyre	205/45Z R16	WEST LAKE	6 mm	
L/H Rear Tyre	205/45Z R16	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/05/2021	Inspection Date	24/05/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	