



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 9418P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR RH TAIL DOOR	BENT	1,350.00	1,350.00
1	REAR BUMPER	BENT	580.00	520.00
1	REAR RH BUMPER SIDE	DENTED	359.00	215.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	450.00	-
1	REAR BUMPER TOW COVER	DENTED	55.00	55.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	450.00	-
1	REAR RH DOOR "PANTER" EMBLEM	NECESSARY	49.50	49.50
	LESS 10% DISCOUNT		-329.35	-218.95
			2,964.15	1,970.55
<u>SPECIAL NETT ITEMS</u>				
1	REAR DOOR COMPANY LETTERING (SN)	NECESSARY	400.00	180.00
1	REAR RH DOOR 6PAX STICKER (SN)	NECESSARY	15.00	12.00
1	REAR RH DOOR GLASS SEALANT (SN)	NECESSARY	40.00	40.00
			455.00	232.00
<u>LABOUR</u>				
	TO PUTTY AND SPRAY REPLACED PARTS.		600.00	400.00
	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND REAR END PANEL.		700.00	450.00
			1,300.00	850.00
GRAND TOTAL			4,719.15	3,052.55
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,450.00

Report Ref No. CS/AGI21006103/Kvf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.