

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006109/KQCN2**Date:** 18/11/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00100812000

**Claimant Vehicle
No :** SMX7506G**Insured Vehicle
No :** SME4066D

Date of Loss: 13/05/2021

Nature of Claim: TP

Claim
No: SNM21D202793/C2/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMX7506G**

Make & Model: TOYOTA RAIZE, 1.0 X CVT (A)

Engine No: 1KRK011755

Reg. Date: 28/01/2021 (Man. Year: 2020)

Chassis No: A200A0013073

Colour: Metallic Beige

Odometer: 3829 km

Engine Capacity: 996 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R16	Rear Tyre Size:	195/65R16
Front Left Side:	Dunlop 9 mm	Rear Left Side:	Dunlop 9 mm
Front Right Side:	Dunlop 9 mm	Rear Right Side:	Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,208.90	1,644.45	564.45	25.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	850.00	470.00	35.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,528.90	2,494.45	1,034.45	29.31
+ GST 7.00/7.00% (S\$)	247.02	174.61	72.41	29.31
Nett Amount (S\$)	3,775.92	2,669.06	1,106.86	29.31

INSPECTION

Date of Assignment: 02/06/2021

Date Inspected: 24/05/2021 Inspected At:

K Kim Hin Auto Pte Ltd (HQ)
160 Sin Ming Drive #02-20, Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Nov 2021)
Parts:	144	TOYOTA RAIZE 1.0 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX7506G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	630.00 FL	*630.00 FL
2	1		*REAR BUMPER LOWER	Dented/Cut	664.00 FL	*664.00 FL
3	8		*REAR BUMPER LOWER CLIPS (WHITE)	Necessary	76.80 FL	*76.80 FL
4	1		*O/S REAR BUMPER OUTER GARNISH	Dented	88.00 FL	*88.00 FL
5	1		*O/S REAR BUMPER PARKING SENSOR	Cracked	576.00 FL	*415.00 FL
6	1		*O/S REAR BUMPER SIDE RETAINER	Serviceable	56.00 FL	*- FL
7	12		*REAR BUMPER CLIPS	Necessary	46.80 FL	*46.80 FL
8	1		*REAR END PANEL	Repair	400.00 FL	*- FL
9	1		*REAR END PANEL INNER AIR GRILLE	Dented	99.00 FL	*99.00 FL
10	1		*O/S REAR FENDER INNER SHIELD	Serviceable	120.00 FL	*- FL
11	4		*O/S REAR FENDER INNER SHIELD CLIPS	Not Necessary	15.60 FL	*- FL
12	1		*O/S REAR FENDER WHEEL ARCH GARNISH	Mtg Cracked	110.00 FL	*110.00 FL
13	1		*REAR BUMPER PARKING SENSOR COVER	Cracked	63.00 FL	*63.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,945.20	2,192.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	736.30	548.15
Total Parts (\$\$)	2,208.90	1,644.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS	New	600.00	400.00
2	TO REMOVE AND REFIT REVERSE SENSOR ASSY	New	60.00	50.00
3	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	600.00	400.00
4	TO APPLY UNDERSEALING	New	60.00	0.00
Gross Labour Cost (S\$)			1,320.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >