



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 49T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	CHAFED / SLICED	3,960.00	2,008.00
10	REAR BUMPER CLIPS	NECESSARY	65.00	30.00
1	REAR BUMPER O/S SIDE RETAINER	DAMAGED	75.00	75.00
1	O/S REAR FENDER SPLASH SHIELD	DAMAGED	290.00	290.00
8	O/S REAR FENDER SPLASH SHIELD CLIPS	NECESSARY	52.00	30.00
1	O/S REAR SHOCK ABSORBER	SERVICEABLE	1,130.00	-
1	O/S REAR SHOCK ABSORBER MOUNTING	SERVICEABLE	380.00	-
1	O/S REAR KNUCKLE ARM	SERVICEABLE	1,680.00	-
1	O/S REAR UPPER ARM	SERVICEABLE	1,080.00	-
1	O/S REAR LOWER ARM	SERVICEABLE	620.00	-
1	O/S REAR CONTROL ARM	SERVICEABLE	1,470.00	-
1	O/S REAR WHEEL BEARING HUB	SERVICEABLE	1,270.00	-
1	TYRE PRESSURE SENSOR	SERVICEABLE	480.00	-
	LESS 5% DISCOUNT		-	-121.65
			12,552.00	2,311.35
	<u>SPECIAL NETT ITEMS</u>			
1	O/S REAR WHEEL RIM (SN)	DENTED / WARPED	2,200.00	2,200.00
1	O/S REAR TYRE (SN)	SERVICEABLE	1,200.00	-
			3,400.00	2,200.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO REPAIR, PANEL BEAT AND STRAIGHTEN DAMAGED PARTS AND REPLACE THE ABOVE-MENTIONED PARTS.		850.00	300.00
	TO DISMANTLE / REPLACE O/S REAR SUSPENSION & UNDERCARRIAGE PARTS.	NOT NECESSARY	380.00	-
	TO REPLACE O/S REAR WHEEL RIM & TYRE INCLUDE WHEEL BALANCING.		180.00	30.00
	TO CONDUCT WHEEL ALIGNMENT. (BEFORE & AFTER).		240.00	60.00
	TO CHECK & RESET ELECTRICAL SYSTEM.		350.00	200.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT THE AFFECTED AREAS.		950.00	600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SUPPLY / INSTALL VINYL STICKER FOR REAR BUMPER, REAR FENDER & REAR DOOR.		2,400.00	600.00
			5,350.00	1,790.00
GRAND TOTAL			21,302.00	6,301.35
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CS3/CTI20008358/Evf3e2-1

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.