LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG21006114/AVCE2

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 Date: 13/08/2021

REFERENCE

Insured/Claimant: PHOON YEE WEI Policy No: 2100452593-05

Date of Loss: 20/05/2021 Nature of Claim: OD Claim No: 6049589906SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA479E

Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN002314

Reg. Date: 19/02/2016 (Man. Year: 2015) Chassis No: WAUZZZF46GA021643

Colour: Black Odometer: 77002 km

Engine Capacity: 1395 cc
Market Value/New Car Price: \$\$80,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		19,387.00	11,742.88	7,644.12	39.43
Miscellaneous Items		0.00	0.00	0.00	
Labour		9,002.00	5,352.00	3,650.00	40.55
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	28,389.00	17,094.88	11,294.12	39.78
	- Excess (S\$)	600.00	600.00	0.00	0.00
	(S\$)	27,789.00	16,494.88	11,294.12	40.64
	+ GST 7.00/7.00% (S\$)	1,945.23	1,154.64	790.59	40.64
	Nett Amount (S\$)	29,734.23	17,649.52	12,084.71	40.64

INSPECTION

Date of Assignment: 25/05/2021

Date Inspected: 24/05/2021 Inspected At: 24 BENOI SECTOR
Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1 2	1	*FRONT BUMPER *FRONT BUMPER FIXING PARTS (NPA)	Deformed Not Necessary	2,111.00 FS 0.00 FS	*1,688.80 FS *-FS
3	2	*FRONT BUMPER SECURING STRIP	Damaged	71.00 FS	*56.32 FS
4	1	*FRONT BUMPER CENTER GRILLE - CENTER	Not Necessary	196.00 FS	*-FS
5	1	*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	210.00 FS	*- FS
6	1	*FRONT BUMPER AIR GUIDE - RH	Not Necessary	63.00 FS	*- FS
7	1	*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	365.00 FS	*- FS
8	1	*RADIATOR GRILLE	Cracked		*1,455.20 FS
9	1	*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	124.00 FS	*- FS
10	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	845.00 FS	*- FS
11	1	*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
12	1	*FRONT BUMPER GUIDE SECTION - RH	Damaged	38.00 FS	*29.84 FS
13	1	*CAUTION STICKER	Not Necessary	14.00 FS	*-FS
14	1	*A/C STICKER	Not Necessary	8.00 FS	*- FS
15	1	*FRONT LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*-FS
16	1	*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	58.00 FS	*-FS
17	1	*HORN - RH	Not Necessary	126.00 FS	*-FS
1 <i>1</i> 18	1	*HORN BRACKET - RH	Not Necessary	29.00 FS	*- FS
		-	Distorted		*613.20 FS
19	1	*FRONT FENDER - RH		767.00 FS	
20	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	202.00 FS	*- FS
21	1	*FRONT FENDER CLOSING ELEMENT - RH	Distorted	72.00 FS	*57.52 FS
22	1	*FRONT FENDER BRACKET - RH	Distorted	35.00 FS	*27.92 FS
23 24	1 1	*FRONT FENDER DEFORMATION BRACKET - RH *FRONT FENDER RIVET (7PCS)	Not Necessary Necessary	49.00 FS 24.00 FS	*- FS *18.48 FS
25	1	*FRONT FENDER BRACE - RH	Bent	118.00 FS	*94.40 FS
26	2	*FRONT FENDER TOP COVER	Deformed	54.00 FS	*42.56 FS
27	1	*FRONT WHEEL HOUSING LINER - RH	Deformed	241.00 FS	*192.80 FS
28	1	*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - R		0.00 FS	*-FS
29	1	*FRONT WHEEL SPOILER - RH	Not Necessary	73.00 FS	*- FS
30	1	*STONE CHIP GUARD	Not Necessary	51.00 FS	*-FS
31	1	*FRONT HEADLIGHT - RH	Cracked	7.693.00 FS	*6,154.40 FS
32	1	*FRONT HEADLIGHT POWER MODULE - RH	Not Necessary	761.00 FS	*- FS
33	1	*FRONT HEADLIGHT CONTROL UNIT - RH	Not Necessary	751.00 FS	*- FS
34	1	*FRONT HEADLIGHT HOSE - RH	Not Necessary	36.00 FS	*- FS
35	1	*FRONT LIFT CYLINDER - RH	Cracked	210.00 FS	*167.60 FS
36	1	*FRONT LIFT CYLINDER BRACKET - RH	Necessary	6.00 FS	*4.80 FS
37	1	*FRONT LIFT CYLINDER HOSE	Not Necessary	93.00 FS	*- FS
38	4	*FRONT RADIATOR AIR GUIDE	Not Necessary	78.00 FS	*-FS
39	1	*FRONT NO. PLATE	Necessary	60.00 FS	*60.00 FS
39 40	1	*SUNDRIES	Necessary	350.00 FS	
-	-				
41	1	*FRONT LOCK CARRIER (Supplementary)	Cracked	1,016.00 FS	*812.80 FS
42	1	*COOLANT (Supplementary)	Necessary	266.00 FS	*212.64 FS
43	1	*HEADLIGHT COMPENSATING PICECE (Supplementary)	Damgaed	40.00 FS	*31.84 FS
F=Fra	ınchise	part. S=SpcNett.	Total Parts (S\$)	19,387.00	11,742.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTSS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET	New	3,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO REMOVE AND REINSTALL AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. (Supplementary)		1,200.00	1,200.00
7	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. (Supplementary)	New	1,800.00	1,250.00
	Gross Labour	r Cost (S\$)	9,002.00	5,352.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >