

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21006119/EQF3E2

Date: 30/06/2021

REFERENCE

Insured/Claimant:	NG CHOON HUAT	Policy No:	1800052198-03	
Date of Loss:	20/05/2021	Nature of Claim:	OD	Claim No: 3399537773SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB5347P	Engine No:	4B11RG7588
Make & Model:	MITSUBISHI ASX, 2.0 (A)	Chassis No:	JMFXTGA2WFZC12804
Reg. Date:	13/04/2016 (Man. Year: 2016)	Odometer:	110811 km
Colour:	Red		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$55,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,204.50	7,855.47	1,349.03	14.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,440.00	3,960.00	1,480.00	27.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,644.50	11,815.47	2,829.03	19.32
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	14,044.50	11,215.47	2,829.03	20.14
+ GST 7.00/7.00% (S\$)	983.12	785.08	198.04	20.14
Nett Amount (S\$)	15,027.62	12,000.55	3,027.07	20.14

INSPECTION

Date of Assignment:	25/05/2021	
Date Inspected:	25/05/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	7.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH CASING	Bent	50.00 FS	*50.00 FS
2	1		*SUNDRY	Necessary	30.00 FS	*20.00 FS
3	1		*FACE, FR BUMPER	Broken	1,041.00 FL	*1,041.00 FL
4	1		*GRILLE, RADIATOR	Cut	266.00 FL	*266.00 FL
5	1		*GARNISH, FR BUMPER, CTR	Broken	845.00 FL	*845.00 FL
6	1		*GARNISH, FR BUMPER, LH	Not Necessary	27.00 FL	*- FL
7	1		*GARNISH, FR BUMPER, RH	Not Necessary	27.00 FL	*- FL
8	1		*REINFORCEMENT, FR BUMPER	Bent	53.00 FL	*53.00 FL
9	1		*CORE, FR BUMPER	Broken	12.00 FL	*12.00 FL
10	1		*CORE, FR BUMPER	Broken	14.00 FL	*14.00 FL
11	1		*REINFORCEMENT, FR BUMPER	Bent	417.00 FL	*417.00 FL
12	1		*COVER, FR BUMPER	Crushed	66.00 FL	*66.00 FL
13	5		*CLIP, ENG ROOM COVER	Not Necessary	20.00 FL	*- FL
14	1		*COVER, HEADLAMP SUPT PANEL	Broken	135.00 FL	*135.00 FL
15	1		*GRILLE, FR BUMPER	Broken	319.00 FL	*319.00 FL
16	1		*HOOD	Dented	822.00 FL	*822.00 FL
17	1		*HINGE, HOOD, LH	Bent	68.00 FL	*68.00 FL
18	1		*HINGE, HOOD, RH	Bent	68.00 FL	*68.00 FL
19	1		*INSULATOR, HOOD	Not Necessary	127.00 FL	*- FL
20	8		*CLIP, HOOD INSULATOR	Not Necessary	24.00 FL	*- FL
21	2		*WEATHERSTRIP, HOOD SIDE	Not Necessary	38.00 FL	*- FL
22	1		*LATCH, HOOD	Not Necessary	76.00 FL	*- FL
23	1		*PNL, HEADLAMP SUPT, UPR LH	Bent	78.00 FL	*78.00 FL
24	1		*PNL, HEADLAMP SUPT, UPR RH	Bent	78.00 FL	*78.00 FL
25	1		*PANEL, HEADLAMP SUPPORT	Bent	368.00 FL	*368.00 FL
26	1		*MOULDING, FR WHEEL ARCH, LH	Necessary	132.00 FL	*132.00 FL
27	1		*MOULDING, FR WHEEL ARCH, RH	Necessary	132.00 FL	*132.00 FL
28	1		*HEADLAMP ASSY, LH	Broken	828.00 FL	*828.00 FL
29	1		*HEADLAMP ASSY, RH	Broken	828.00 FL	*828.00 FL
30	1		*CONDENSER ASSY, A/C REFRIGE	Bent	1,140.00 FL	*1,140.00 FL
31	1		*PIPE, A/C CONDENSER OUTLET	Bent	202.00 FL	*202.00 FL
32	1		*HOSE, A/C COMPR DISCHARGE	Not Necessary	197.00 FL	*- FL
33	1		*RADIATOR ASSY	Bent	1,157.00 FL	*1,157.00 FL
34	1		*CAP ASSY, RADIATOR	Not Necessary	91.00 FL	*- FL
35	1		*FAN, COOLING LH	Not Necessary	74.00 FL	*- FL
36	1		*FAN, COOLING, RH	Not Necessary	70.00 FL	*- FL
37	1		*SHROUD, COOLING FAN	Not Necessary	274.00 FL	*- FL
38	1		*MOTOR, COOLING FAN, LH	Jammed	474.00 FL	*474.00 FL
39	1		*MOTOR, COOLING FAN, RH	Not Necessary	467.00 FL	*- FL
40	1		*DUCT, A/CLNR INTAKE	Not Necessary	227.00 FL	*- FL
41	1		*WEATHERSTRIP, HOOD (Supplementary)	Torn	74.00 FL	*74.00 FL
42	1		*GARNISH, FR DECK, LH (Supplementary)	Cut	92.00 FL	*92.00 FL
43	1		*GARNISH, FR DECK, RH (Supplementary)	Cut	92.00 FL	*92.00 FL
44	10		*CLIP, TRUNK ROOM TRIM (Supplementary)	Necessary	30.00 FL	*30.00 FL
45	20		*CLIP, RR BUMPER (Supplementary)	Necessary	60.00 FL	*60.00 FL
46	1		*PANEL, HEADLAMP SUPPORT, LH (Supplementary)	Bent	44.00 FL	*44.00 FL
47	10		*RIVET, FR BUMPER (Supplementary)	Necessary	50.00 FL	*50.00 FL
48	1		*HORN (Supplementary)	Bent	82.00 FL	*82.00 FL
49	1		*PANEL, HEADLAMP SUPPORT, RH (Supplementary)	Bent	44.00 FL	*44.00 FL

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT SUPPORT & BONNET. REPAIR LHF FENDER & RHF FENDER	New	3,200.00	1,800.00
2	RESPRAY FRT BUMPER, BONNET, FRT SUPPORT, LHF FENDER & RHF FENDER	New	1,750.00	1,750.00
3	REMOVE & REFIT AC CONDENSER & RADIATOR	New	100.00	100.00
4	TOP UP AIRCON GAS	New	80.00	80.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
8	SUPPLY BODY PNL SEALANT	New	80.00	40.00
Gross Labour Cost (\$)			5,440.00	3,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >