

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711**Our File No:** CS/III21006127/EQF3Q2**Date:** 29/06/2021**REFERENCE**Insured/Claimant: PAN PACIFIC VAN & TRUCK LEASING PTE LTD
Date of Loss: 18/05/2021Policy No: D19MFL0005549_01
Nature of Claim: OD
Claim No: MFL2021D0002162**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	GBH316Z	Engine No:	ZD30026444N
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Chassis No:	JN1SC2F24Z0860987
Reg. Date:	27/12/2017 (Man. Year: 2017)	Odometer:	15420 km
Colour:	Red		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	S\$55,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	TRAVIA 5 mm	Rear Left Side:	TRAVIA 5 mm
Front Right Side:	TRAVIA 5 mm	Rear Right Side:	TRAVIA 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,646.00	1,682.50	4,963.50	74.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,330.00	770.00	36.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,746.00	3,012.50	5,733.50	65.56
Approved Total (Overridden) (S\$)		1,600.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00

(S\$)	7,246.00	100.00	7,146.00	98.62
+ GST 7.00/7.00% (S\$)	507.22	7.00	500.22	98.62
Nett Amount (S\$)	7,753.22	107.00	7,646.22	98.62

INSPECTION

Date of Assignment: 25/05/2021

Date Inspected: 25/05/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Efficient Motor & Engineering Works Pte Ltd (HQ)
 56 Loyang Way #06-07, Loyang Enterprise Building
 Singapore 508775

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Jun 2021)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH316Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WIPER PANEL (WCP)	Repair	300.00 F	*- F
2	1		*FRONT PANEL (WCP)	Dented	580.00 F	*580.00 F
3	1		*FRONT GRILLE (WCP)	Not Necessary	230.00 F	*- F
4	1		*FRONT GRILLE LOGO (WCP)	Not Necessary	40.00 F	*- F
5	1		*FRONT BUMPER WITH REINFORCEMENT (WCP)	Broken	500.00 F	*500.00 F
6	1		*HEADLAMP LOWER GARNISH LH/RH (WCP)	N/S Broken	110.00 F	*55.00 F
7	1		*HEADLAMP LH/RH (WCP)	N/S Broken	480.00 F	*240.00 F
8	2		*FRONT CORNER PANEL LH/RH (WCP)	Not Necessary	370.00 F	*- F
9	1		*STEERING COLUMN ASSY (WCP)	Not Necessary	750.00 F	*- F
10	1		*STEERING COLUMN JOINT LOWER (WCP)	Not Necessary	200.00 F	*- F
11	1		*STEERING TRANSFER GEAR (WCP)	Not Necessary	550.00 F	*- F
12	1		*FRONT CABIN SHAFT (WCP)	Not Necessary	400.00 F	*- F
13	2		*FRONT CABIN MOUNTING LH/RH (WCP)	Not Necessary	300.00 F	*- F
14	2		*FRONT UPPER FINISHER LH/RH (WCP)	Not Necessary	300.00 F	*- F
15	1		*RADIATOR (WCP)	Not Necessary	650.00 F	*- F
16	1		*FRONT NUMBER PLATE	Cut	40.00 FS	*40.00 FS
17	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
18	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
19	1		*REDMART STICKER	Necessary	100.00 FS	*50.00 FS
20	1		*TOWING FEE	Necessary	70.00 FS	*70.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	6,070.00	1,545.00
+ Margin on L,N Items 10.00/10.00% (S\$)	576.00	137.50
Total Parts (S\$)	6,646.00	1,682.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CUT/WELD FRONT PANEL ,WIPER PANEL AND OTHER DAMAGED PANELS TO REMOVE & REPLACE DAMAGED PARTS	New	800.00	600.00
2	TO CHECK AND RECTIFY LIGHTING & WIRING	New	50.00	30.00
3	TO SPRAY PAINTING FRONT PORTIONS	New	800.00	500.00
4	TO REMOVE & REFIT DASHBOARD TO FACILITATE REPAIR	New	250.00	200.00
5	TO REMOVE AND REFIT STEERING COMPONENTS	New	200.00	0.00
Gross Labour Cost (S\$)			2,100.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >