

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS/AIG21006129/EVF3E2

**Date:** 08/07/2021

### REFERENCE

Insured/Claimant:	CHENG GEOK CHIN	Policy No:	
Date of Loss:	24/05/2021	Nature of Claim:	OD Claim No: 5833282184SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EU6008U	Engine No:	3A92UGS5312
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AJH001861
Reg. Date:	23/03/2018 (Man. Year: 2018)	Odometer:	19925 km
Colour:	Red		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$52,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,917.93	6,059.17	1,858.76	23.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,270.00	6,795.00	1,475.00	17.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>16,187.93</b>	<b>12,854.17</b>	<b>3,333.76</b>	<b>20.59</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,133.16</b>	<b>899.79</b>	<b>233.37</b>	<b>20.59</b>
<b>Nett Amount (S\$)</b>	<b>17,321.09</b>	<b>13,753.96</b>	<b>3,567.13</b>	<b>20.59</b>

### INSPECTION

Date of Assignment: 25/05/2021

Date Inspected: 25/05/2021 Inspected At:

Estimated Period of Repair: 17.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*HOOD	Dented	737.00 FL	*737.00 FL
3	1		*FACE, FR BUMPER	Broken	706.00 FL	*706.00 FL
4	1		*GARNISH, FR BUMPER, RH	Cut	127.00 FL	*127.00 FL
5	1		*HEADLAMP ASSY, RH	Broken	663.00 FL	*663.00 FL
6	1		*FENDER, FR RH	Dented	500.00 FL	*500.00 FL
7	1		*SHIELD, FR WHEELHOUSE, RH	Crushed	98.00 FL	*98.00 FL
8	1		*GARNISH, FR PILLAR, RH	Missing	30.00 FL	*30.00 FL
9	1		*GARNISH, FR FENDER	Not Necessary	65.00 FL	*- FL
10	1		*MIRROR ASSY, DOOR, RH	Cut	641.00 FL	*641.00 FL
11	1		*COVER, DOOR MIRROR, OTR RH	Missing	115.00 FL	*115.00 FL
12	1		*PANEL ASSY, FR DOOR, RH	Dented	1,001.00 FL	*1,001.00 FL
13	1		*MLDG, F/DR WDO BELT LINE, RH	Bent	75.00 FL	*75.00 FL
14	1		*W/STRIP, FR DR OPNG, OTR RH	Not Necessary	144.00 FL	*- FL
15	1		*HANDLE, FR DOOR OUTSIDE, RH	Not Necessary	101.00 FL	*- FL
16	1		*PANEL ASSY, RR DOOR, RH	Dented	803.00 FL	*803.00 FL
17	1		*MLDG, R/DR WDO BELT LINE, RH	Not Necessary	66.00 FL	*- FL
18	1		*W/STRIP, R/DR OPNG, OTR RH	Not Necessary	136.00 FL	*- FL
19	1		*W/STRIP, R/DR STAT WDO, RH	Not Necessary	55.00 FL	*- FL
20	1		*WHEEL, DISC	Cut	687.00 FL	*687.00 FL
21	1		*TAPE, FR DOOR SASH, RH	Necessary	29.00 FL	*29.00 FL
22	1		*TAPE, RR DOOR SASH, RH	Necessary	29.00 FL	*29.00 FL
23	1		*EMBLEM ECO	Necessary	17.00 FS	*17.00 FS
24	1		*UNPAINTED BODYKITS	Repair	1,643.00 FN	*- FN
25	1		*HANDLE, FR DOOR OUTSIDE, RH	Not Necessary	101.00 FL	*- FL
26	1		*PANEL, QTR, OTR RH	Dented	767.00 FL	*767.00 FL
27	1		*TRIM,FR DOOR SASH,RH	Necessary	33.00 FL	*33.00 FL
28	1		(Supplementary) *TRIM,FR DOOR,RH	Crushed	525.00 FL	*525.00 FL
29	1		(Supplementary) *HINGE,FR DOOR,UPR,RH	Bent	54.00 FL	*54.00 FL
30	1		(Supplementary) *SENSOR,FR ABS	Torn	171.00 FL	*171.00 FL
31	6		(Supplementary) *RIVET,FR BUMPER	Necessary	30.00 FL	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	10,199.00	7,858.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,952.47	1,798.83
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	328.60	0.00
Total Parts (\$\$)	7,917.93	6,059.17

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE HOOD, FRT BUMPER, FRT RH FENDER, RH FRT & REAR DOOR, RH REAR QUARTER PANEL, RH SIDE MIRROR ASSY & AFFECTED AREAS	New	3,600.00	2,925.00
2	SPRAY PAINT WORK ON HOOD, FRT BUMPER, FRT RH FENDER, RH FRT & REAR DOOR, RH REAR QUARTER PANEL, RH A-PILLAR, RH WING MIRROR COVER & FRT, BODYKIT	New	3,150.00	2,530.00
3	TO APPLY BODY SEALANT ON AFFECTED AREAS	New	120.00	120.00
4	TO TRANSFER RH FRT & REAR ATTACHMENTS TO NEW PANEL	New	240.00	240.00
5	CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	TO PERFORM RUST PREVENTION	New	160.00	40.00
8	TO TRANSFER FRT LH RIM INCLUDING BALANCING	New	30.00	30.00
9	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
10	TO REMOVE AND INSTALL REAR WINDSHIELD GLASS TO FACILITATE REPAIR	New	240.00	240.00
11	TO APPLY WINDSHIELD SEALANT	New	80.00	80.00
12	TO REMOVE AND INSTALL REAR SEAT COMPARTMENT TO FACILITATE REPAIR	New	150.00	120.00
13	TO REMOVE AND INSTALL REAR BOOT COMPARTMENT TO FACILITATE REPAIR	New	150.00	120.00
14	R&R BODY KIT	New	80.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,270.00</b>	<b>6,795.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >