

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21006131/UQY3E2**Date:** 17/10/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900242766
Claimant Vehicle No :	MDC6175	Insured Vehicle No :	SMQ2932D
Date of Loss:	29/11/2020	Nature of Claim:	TP
		Claim No:	2110932730SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	MDC6175	Engine No:	HIDDEN
Make & Model:	YAMAHA YZF-R25, 250cc	Chassis No:	PMYRG1510J0015043
Reg. Date:	01/11/2018 (Man. Year: 2018)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	250 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	150/60-17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	25/05/2021	
Date Inspected:	25/05/2021	Inspected At: Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: RM18,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Broken	0.00 F	*- F
2	1		*FRONT SPORT RIM	Bent	0.00 F	*- F
3	1		*FRONT BRAKE DISC	Warped	0.00 F	*- F
4	1		*FRONT AXLE WHEEL	Bent	0.00 F	*- F
5	1		*FRONT TYRE	Cut	0.00 F	*- F
6	1		*FRONT FORK LH	Bent	0.00 F	*- F
7	1		*FRONT FORK RH	Bent	0.00 F	*- F
8	1		*FRONT STEERING STEM	Bent	0.00 F	*- F
9	1		*HEADLAMP	Cracked	0.00 F	*- F
10	1		*FRONT COWLING	Cracked	0.00 F	*- F
11	1		*FRONT WINDSCREEN COVER	Broken	0.00 F	*- F
12	1		*FRONT HORN UNIT	Dented	0.00 F	*- F
13	1		*FRONT SIGNAL LAMP	Cracked	0.00 F	*- F
14	1		*SET FRONT FAIRING	Broken	0.00 F	*- F
15	1		*METER	Damaged	0.00 F	*- F
16	1		*HEADLAMP STAY	Bent	0.00 F	*- F
17	1		*CLUTCH LEVEL	Scratched	0.00 F	*- F
18	1		*REAR EXHAUST	Bent	0.00 F	*- F
19	1		*EXHAUST HEADER	Distorted	0.00 F	*- F
20	1		*FUEL TANK	Repair	0.00 F	*- F
21	1		*SET SLIDER	Cut	0.00 F	*- F
22	1		*AIR INTAKE	Cut	0.00 F	*- F
23	1		*HANDLE BAR LH	Bent	0.00 F	*- F
24	1		*HANDLE BAR RH	Bent	0.00 F	*- F
25	1		*RADIATOR	* Check	0.00 F	*- F
26	1		*RADIATOR COWLING	* Check	0.00 F	*- F
27	1		*SIDE BOARD LH	Cut	0.00 F	*- F
28	1		*REAR FOOTREST RH	Cut	0.00 F	*- F
29	1		*MIRROR LH	Broken / Missing	0.00 F	*- F
30	1		*STEERING STEM TOP	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)
0.00
0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >