

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21006139/UUF3Q2  
**Date:** 08/06/2021

### REFERENCE

|                              |                                      |                             |            |
|------------------------------|--------------------------------------|-----------------------------|------------|
| Handling Insurer:            | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:                  | 1001509059 |
| <b>Claimant Vehicle No :</b> | XE5011A                              | <b>Insured Vehicle No :</b> | WC3970S    |
| Date of Loss:                | 24/05/2021                           | Nature of Claim:            | TP         |
|                              |                                      | Claim No:                   | 257876     |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                          |             |                |
|-----------------------------|------------------------------------------|-------------|----------------|
| Reg No:                     | <b>XE5011A</b>                           |             |                |
| Make & Model:               | MITSUBISHI FUSO, 10.7 D FV70HJA00064 (M) | Engine No:  | 470912C0460317 |
| Reg. Date:                  | 22/07/2019 (Man. Year: 2019)             | Chassis No: | FV70HJA00137   |
| Colour:                     | White                                    | Odometer:   | 135155 km      |
| Engine Capacity:            | 10677 cc                                 |             |                |
| Market Value/New Car Price: | N/A                                      |             |                |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>        |             |                |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

### CONDITION OF TYRES

|                   |              |                  |                    |
|-------------------|--------------|------------------|--------------------|
| Front Tyre Size:  | 295/80R22.5  | Rear Tyre Size:  | 295/80R22.5 (D/D)  |
| Front Left Side:  | Firenza 5 mm | Rear Left Side:  | Firenza 5/5/5/5 mm |
| Front Right Side: | Firenza 5 mm | Rear Right Side: | Firenza 5/5/5/5 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 9,479.42          | 4,231.37          | 5,248.05          | 55.36         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 3,530.00          | 1,930.00          | 1,600.00          | 45.33         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>13,009.42</b>  | <b>6,161.37</b>   | <b>6,848.05</b>   | <b>52.64</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>4,900.00</b>   |                   |               |

|                               |                  |                 |                 |              |
|-------------------------------|------------------|-----------------|-----------------|--------------|
| (S\$)                         | 13,009.42        | 4,900.00        | 8,109.42        | 62.33        |
| <b>+ GST 7.00/7.00% (S\$)</b> | 910.66           | 343.00          | 567.66          | 62.34        |
| <b>Nett Amount (S\$)</b>      | <b>13,920.08</b> | <b>5,243.00</b> | <b>8,677.08</b> | <b>62.33</b> |

INSPECTION

Date of Assignment: 25/05/2021

Date Inspected: 25/05/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Mah Lian Motor Vehicle Repairer (HQ)  
 NO. 38 DEFU LANE 9  
 Singapore 539278

**Adjuster:** MARCUS CHUA**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                           |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 07 Jun 2021)                                                                                                                                             |                                                                           |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | mitsubishi fuso 10.7 D FV70HJA00064 (M) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                         |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for XE5011A)                                                                                                                                     |                                                                           |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                           |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                           |

### Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition           | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------|---------------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                      | Bent / Twisted      | 3,081.29 FL | *2,645.41 FL |
| 2   | 1   |          | *FRONT BUMPER SIDE CORNER-RH       | Distorted           | 155.06 FL   | *135.25 FL   |
| 3   | 1   |          | *FRONT BUMPER BLACK CLIP           | Cracked             | 193.73 FL   | *182.36 FL   |
| 4   | 1   |          | *FRONT CORNER PANEL -RH            | Distorted / Cracked | 564.77 FL   | *564.77 FL   |
| 5   | 1   |          | *FRONT CORNER BRACKET -RH          | Distorted           | 354.20 FL   | *354.20 FL   |
| 6   | 1   |          | *FRONT CORNER PANEL RUBBER SEAL-RH | Torn                | 143.64 FL   | *143.64 FL   |
| 7   | 1   |          | *FRONT DOOR -RH                    | Repair              | 3,182.28 FL | *- FL        |
| 8   | 1   |          | *FRONT DOOR LAMP -RH               | Scratched           | 123.36 FL   | *123.36 FL   |
| 9   | 1   |          | *FRONT DOOR PILLAR -RH             | Repair              | 1,589.54 FL | *- FL        |
| 10  | 1   |          | *HEADLAMP ASSY -RH                 | Cracked             | 1,543.74 FL | *1,004.36 FL |
| 11  | 1   |          | *FOG LAMP -RH                      | Not Necessary       | 361.14 FL   | *- FL        |
| 12  | 1   |          | *HEADLAMP HOUSING -RH              | Broken / Missing    | 366.26 FL   | *355.15 FL   |
| 13  | 1   |          | *HEADLAMP STAY -RH                 | Not Necessary       | 340.22 FL   | *- FL        |
| 14  | 1   |          | *LOGO ADVERTISEMENT                | Necessary           | 480.00 FS   | *100.00 FS   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                           |                  |                 |
|-----------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (S\$)</b>                                    | <b>12,479.23</b> | <b>5,608.50</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (S\$)</b> | 2,999.81         | 1,377.13        |
| <b>Total Parts (S\$)</b>                                  | <b>9,479.42</b>  | <b>4,231.37</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                       | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-----------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <u>Labour Items</u>            |                                                                                   |          |                 |                 |
| 1                              | LABOUR TO REMOVE & REFIT HEADLAMP ,FOG LAMP & TO CHECK WIRING & REFOCUS ALL LIGHT | New      | 200.00          | 30.00           |
| 2                              | LABOUR CHARGE TO CUT & WELD & DISMANTLE & REMOVE & REFIT ALL ABOVE PARTS          | New      | 1,200.00        | 1,000.00        |
| 3                              | TO SPRAY & PAINTING AT ACCIDENT AFFECTED AREA                                     | New      | 1,500.00        | 900.00          |
| 4                              | TO RUST PROOFING AT ACCIDENT AFFECTED AREA                                        | New      | 180.00          | 0.00            |
| 5                              | LABOUR TO REMOVE & REFIT FRONT DOOR RH & TRANSFER PARTS & REALIGNMENT             | New      | 450.00          | 0.00            |
| <b>Gross Labour Cost (S\$)</b> |                                                                                   |          | <b>3,530.00</b> | <b>1,930.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >