BLOCK 607 ELIAS ROAD #05-192 SINGAPORE (510607) BUSINESS REGN. No. 53193457L Hp 96699986

INVOICE

Leong Guo Wei, Elwin Mr

Block 671A Yishun Avenue 4 #12-604

Singapore 761671

Invoice No

: PA/2103/0004/tpw

Our Ref

: PA/FBN6370/0221/tpw

Date

: 08 March 2021

Claim Type	Third Party	Date of Accident	27 January 2021
Vehicle No.	FBN 6370 U	Date of Inspection	04 February 2021
No	Description	1.	Amount (S\$)
1 Survey fees inclusive of Transportation and Photographs (66) copies			\$526.00
,			

Singapore Dollar: Five Hundred And Twenty-Six Only

All payments made payable to : Prudent Adjustors Services

Prudent Adjustors Services Bok Jee Tan

BLOCK 607 ELIAS ROAD #05-192 SINGAPORE 510607 BUSINESS REGN. No. 53193457L HP: 96699986

VEHICLE DAMAGE INSPECTION REPORT

Мг

Leong Guo Wei, Elwin

Block 671A Yishun Avenue 4 #12-604

Singapore 761671

Our Ref

: PA/FBN6370/0221/tpw

Date

: 08 March 2021

REFERENCES

Claim Type Vehicle No. : Third Party

: FBN 6370 U

Date of Accident

: 27 January 2021

Make

: Honda

Date of Assignment Date of Inspection

: 04 February 2021 : 04 February 2021

Model

Date of Re-inspection

: 24 February & 05 March 2021

Reg. Date

: CB150R Manual : 15 November 2018

COE Expiry

: 14 November 2028

Color

: Green

Chassis No

: MLHKC288XJ5028136

Odometer

: No Key

Engine No

: Blocked

TYRE CONDITION

Make

Size

Thread Balance

Front

Dunlop

110/70-17

5mm 6mm

Rear

Dunlop

150/60-17

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at frontal and both sides.

Please refer to photographs and assessment of repairs for details Enclosed (66) photographs depicting damages and after repaired

INSPECTION AND ADJUSTMENT

Original Quotation

\$7,853.39

Revised Assessment

\$5,600.00 Lump sum

Survey conducted at E Motoring Pte Ltd

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately Eight (8) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note:

The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock Reconditioned parts whichever is possible

Vehicle No: FBN 6370 U Our Ref : PA/FBN6370/0221/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

				Original	Revised
S/N	Description Material	Qty	Condition	Quotation	Quotation
1	Handle bar	1 pc	Bent	110.00	110.00 🗸
2	Handle bar balancer \checkmark	1 set	Cut	80.00	80.00 48
3	Throttle cable X SVC	1 set	Cut	55.00	55.00 ×
4	Brake lever X SVC	1 pc	Bent/cut	52.80	52.80 ×
5	Front brake master pump assy X SVC	1 pc	Cut	217.50	217.50 🗙
6	Clutch lever \checkmark	1 pc	Bent	48.00	48.00 🗸
7	Mirror ✓	1 set	Cut/bent	120.00	120.00 60
8	Headlight (LED) 🗸	1 pc	Cracked/grazed	658.00	658.00 380
9	Head light cover	1 pc	Grazed/cut	86.00	86.00 ✓
10	Front signal (LED) @ \$117/- ✓	2 pcs	Grazed/cut RH	234.00	117.00 🗸
11	Front fork assy @ \$569.50/- \/	2 pcs	Bent	1,139.00	1,139.00 🗸
12	Stem steering \checkmark	1 pc	Distorted	220.60	220.60 🗸
13	Front fender \checkmark	1 pc	Cracked	98.30	98.30 🗸
14	Front wheel rim 🗸	1 pc	Cracked	533.80	533.80 🗸
15	Front wheel rim axle	1 pc	Bent	66.40	66.40 🗸
16	Front brake disc X SVC	1 pc	Warped	185.00	185.00 ×
17	Fuel tank cover RH 🗸	1 pc	Cut	118.40	118.40 🗸
18	Front shroud RH X SVC	1 pc	Cracked/cut	105.50	105.50 🗙
19	Front shroud inner RH	1 pc	Serviceable	88.50	~
20	Radiator assy 🗸	1 pc	Dented	350.60	350.60 🗸
21	Lower cover RH 🗸	1 pc	Cut	78.80	78.80 🗸
22	Front footrest assy RH X SVC	1 pc	Broken	58.00	58.00 ×
23	Front footrest bracket RH X SVC	1 pc	Bent	110.00	110.00 ×
24	Brake pedal X SVC	1 pc	Cut / Bent	65.00	65.00 ×
25	Exhaust muffler cover 🗸	1 pc	Cut	224.90	224.90 145
26	Rear footrest RH ✓	1 pc	Cut	62.00	62.00 🗸
27	Rear footrest bracket RH X SVC	1 pc	Cut	101.00	101.00 ×
28	Tail cover RH	1 pc	Serviceable	150.00	~
29	Rear wheel rim 🗸	1 pc	Cut	620.00	620.00 🗸
	•	-		6,037.10	5,681,60 4281.
	List price less 10%			603.71	568.16
				5,433.39	5,113.44

Vehicle No: FBN 6370 U Our Ref : PA/FBN6370/0221/tpw

30 31 32 33 34 35	Special nett item Steering cone & bearing Front wheel rim bearing X SVC Rear wheel rim bearing X SVC Body sticker "CB150R" X SVC Front tyre (Dunlop 110/70-R17) Rear tyre (Dunlop 150/60-R17)	✓	1 set 1 pc 1 pc 1 set 1 pc 1 pc	Necessary Necessary Necessary Necessary Puncture Puncture	180.00 60.00 80.00 120.00 160 180.00 180 250.00	90.00 40.00 60.00 80.00 160.00 128 220.00 144 650.00 362
	Labours					
	Transportation (2 trips)				150.00	120.00 50
	Body chassis repair & alignment				550.00	450.00 🗙
	Swing arm repair & align				350.00	280.00 🔀
	To repair, renew damaged parts				500.00	400.00 300
					1,550.00	1,250.00
	Total parts & labour concluded			4565.71	<u>7,853.39</u>	7.013.44
	A.			-20%: 3650		
	Lump sum repair adjustment			4.0-		<u>5,600.00</u>
				4 Days		

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.

Prudent Adjustors Services Bok Jee Tan