



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2104425

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 23/06/2021
Reference CC4/FCI21006146/R1ea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBF 3765B
Insured Veh. YM 1615E
Claim No. D21001610MFCV
Policy No. D-20095987MFCV
Accident Date 24/05/2021
Inspection Date 27/05/2021

Description	Total
Survey Inspection	311.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	311.00
GST (7%)	21.77
Grand Total	332.77

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21006146/R1ea3q2	
			Date: 23/06/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 1615E	Veh. Inspected	GBF 3765B	
Policy No.	D-20095987MFCV	Coverage (\$)	0.00	
Claim No.	D21001610MFCV	Excess (\$)	0.00	
Assign From	VIC	Assign Date	27/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	FIAT DOBLO CARGO MAXI 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZFA26300006C64059	Colour	WHITE	
Odometer	132602 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16C	TRANSWAY	6 mm	
L/H Front Tyre	195/60 R16C	TRANSWAY	6 mm	
R/H Rear Tyre	195/60 R16C	TRANSWAY	6 mm	
L/H Rear Tyre	195/60 R16C	TRANSWAY	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/05/2021	Inspection Date	27/05/2021	
Survey held at	8 TUAS AVE 18			
Repairer	VENDA ENGINEERING & TRADING PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 3765B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR DOOR ,LH	BENT	1,025.30	1,025.30
1	REAR DOOR ,RH	BENT	986.80	986.80
1	REAR DOOR CENTRE LOCK STRIKER ,RH	BENT	47.02	47.02
1	REAR DOOR COVER (OUTER) ,RH	CRACKED	75.39	75.39
1	REAR DOOR COVER LOGO ,RH	NECESSARY	88.14	88.14
1	REAR DOOR GLASS ,LH	BROKEN	262.46	262.46
1	REAR DOOR GLASS ,RH	BROKEN	255.37	255.37
1	REAR DOOR INNER LOCK ,LH	CUT	209.30	209.30
1	REAR DOOR LOCK ASSY (INNER) RH	SERVICEABLE	55.23	-
1	REAR DOOR LOWER LOCK, RH	NOT NECESSARY	166.95	-
1	REAR DOOR UPPER LOCK ,RH	NOT NECESSARY	127.24	-
1	REAR DOOR WEATHERSTRIP	NECESSARY	410.68	410.68
1	REAR WIPER ARM WITH BLADE ,LH	CUT	168.42	168.42
1	REAR WIPER MOTOR ,LH	CRACKED	395.20	395.20
1	REAR WIPER ,LH	BENT	50.00	50.00
1	REAR BUMPER	CUT	797.69	797.69
1	REAR DOOR OUTER HANDLE GARNISH ,LH	CRACKED	367.76	367.76
1	REAR DOOR RUBBER ,RH (ADDITIONAL)	NECESSARY	205.11	205.11
	LESS 10% DISCOUNT		-569.41	-534.46
			5,124.65	4,810.18
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
1	SPEED LIMIT STICKER (SN)	NECESSARY	20.00	10.00
1	PAX STICKER (SN)	NECESSARY	20.00	10.00
1	REAR NUMBER PLATE WITH CASING (SN)	CUT	50.00	35.00
1	SILICONE (SN)	NECESSARY	150.00	100.00
2	PRIMER @\$20.00 (SN)	NECESSARY	40.00	40.00
			480.00	195.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	DISMANTLE & REINSTALL REAR DOOR LH & RH WINDSCREEN .		260.00	160.00
	REMOVE & RENEW THE ABOVE MENTIONED PARTS.		800.00	600.00
	TRANSFER PARTS.		120.00	60.00
	SPRAY PAINT REAR LH & RH DOOR & REAR BUMPER .		650.00	600.00
	REMOVE & RENEW THE REAR RH DOOR RUBBER . (ADDITIONAL)		100.00	60.00
			1,930.00	1,480.00
	GRAND TOTAL		7,534.65	6,485.18
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,200.00

Report Ref No. CC4/FCI21006146/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 3765B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 3765B

RE-INSPECTION

