

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21006147/URA3Q2**Date:** 03/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800046189
<b>Claimant Vehicle No :</b>	SKE3068D	<b>Insured Vehicle No :</b>	SME1155A
Date of Loss:	23/05/2021	Nature of Claim:	TP
		Claim No:	7111138334SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKE3068D</b>	Engine No:	CAV363861
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI 1623Q5 (A)	Chassis No:	WVWZZZ16ZCM082602
Reg. Date:	23/02/2012 (Man. Year: 2011)	Odometer:	192260 km
Colour:	Silver		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Firena 6 mm	Rear Left Side:	Firena 6 mm
Front Right Side:	Firena 6 mm	Rear Right Side:	Firena 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,451.61	3,182.20	1,269.41	28.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	1,200.00	450.00	27.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,101.61</b>	<b>4,382.20</b>	<b>1,719.41</b>	<b>28.18</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>		
<b>(S\$)</b>	6,101.61	3,500.00	2,601.61	42.64
<b>+ GST 7.00/7.00% (S\$)</b>	427.11	245.00	182.11	42.64
<b>Nett Amount (S\$)</b>	<b>6,528.72</b>	<b>3,745.00</b>	<b>2,783.72</b>	<b>42.64</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment:	27/05/2021		
Date Inspected:	27/05/2021	Inspected At:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36 Singapore 417883
Estimated Period of Repair:	4.0 days		

**Adjuster:** MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,622.70 FL	*1,255.10 FL
2	1		*FRONT BUMPER REINFORCEMENT	Dented	688.10 FL	*565.25 FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	86.10 FL	*86.10 FL
4	10		*FRONT BUMPER CLIPS	Necessary	70.00 FL	*50.00 FL
5	1		*FRONT BUMPER SPORGE RH	Torn	110.80 FL	*110.80 FL
6	1		*FOG LAMP RH	Cracked	188.00 FL	*188.00 FL
7	1		*FOG LAMP COVER	Scratched	66.80 FL	*66.80 FL
8	1		*HEAD LAMP RH	Cracked	753.73 FL	*753.73 FL
9	1		*FRONT FENDER	Distorted	460.00 FL	*460.00 FL
10	1		*SPORT RIM ASSY	Repair	900.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	4,946.23	3,535.78
- List Item Discount on L Items 10.00/10.00% (\$)	494.62	353.58
Total Parts (\$)	4,451.61	3,182.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING	New	80.00	0.00
2	TO CHECK WIRING SYSTEM	New	50.00	20.00
3	TO CHECK COMPUTER WHEEL ALIGNMENT	New	120.00	60.00
4	TO RESPRAY AFFECTED AREAS	New	700.00	600.00
5	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR AND ALIGNED ALL PARTS	New	700.00	520.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,650.00</b>	<b>1,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >