

ASS. REC. BY:

REF:

C72/ 21006149/Kt

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLR 2333P

Yr Regn:

08, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1797

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

166146

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZVW 50. 6046773

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

3

mm

L/Bal.

7

mm

L/Bal.

3

mm

D.O.A.

18/5/21

D.O.I.

27/5/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

15 d/s &amp; u/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/11/2021 8:16, 2001

Finalize at \$14250/- Cred: 6590.02 : 31%

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

10

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

07

14250/-

Adjuster recommendation S\$20,840.02 exceeds max mandate of S\$15,450.00 given by the insurer for direct offer.  
Adjuster must seek a new mandate from insurer.

You cannot authorize this offer because  
Adjuster recommendation S\$20,840.02 exceeds max mandate of S\$15,450.00 given by the insurer for direct offer.  
Adjuster must seek a new mandate from insurer.  
File to be authorized by your superior.

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

Our File No: CS/CTI21006149/KTC

Date: 14/07/2021

#### REFERENCE

Insured/Claimant: AUTOBAHN RENT A CAR PTE LTD Policy No: DMHCSNA00004192100  
Date of Loss: 18/05/2021 Nature of Claim: OD Claim No: SNM21D202944/C01/LEWLC

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR2333P  
Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZR6860386  
Reg. Date: 04/08/2017 (Man. Year: 2017) Chassis No: ZVW506046773  
Colour: Silver Odometer: 0 km  
Engine Capacity: 1789 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size:  
Front Left Side: 0 mm Rear Left Side: 0 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                      | Repairer's       | Adjuster's       | Difference      | Diff %      |
|-------------------------------------|------------------|------------------|-----------------|-------------|
| Parts                               | 19,299.00        | 19,299.00        | 0.00            | 0.00        |
| Miscellaneous Items                 | 0.00             | 0.00             | 0.00            |             |
| Labour                              | 982.80           | 982.80           | 0.00            | 0.00        |
| Paintwork Labour                    | 558.22           | 558.22           | 0.00            | 0.00        |
| Towing                              | 0.00             | 0.00             | 0.00            |             |
| <b>Calculated Gross Total (S\$)</b> | <b>20,840.02</b> | <b>20,840.02</b> | <b>0.00</b>     | <b>0.00</b> |
| - Excess (S\$)                      | 0.00             | 2,000.00         | -2,000.00       |             |
| (S\$)                               | 20,840.02        | 18,840.02        | 2,000.00        | 9.60        |
| + GST 7.00/7.00% (S\$)              | 1,458.80         | 1,318.80         | 140.00          | 9.60        |
| <b>Nett Amount (S\$)</b>            | <b>22,298.82</b> | <b>20,158.82</b> | <b>2,140.00</b> | <b>9.60</b> |

#### INSPECTION

Date of Assignment: 25/05/2021 Present Location: Ding Auto Pte Ltd (HQ)  
Date Inspected: 27/05/2021 Inspected At: Ding Auto Pte Ltd (HQ)  
Estimated Period of Repair: 10.0 days 176 Sin Ming Drive #04-06, Sin Ming Autocare  
Singapore 575721

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



**REPAIR DETAILS****Reference**

|                      |                                                                                                                                                                              |                                                                   |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 25 May 2021)                     |
| <b>Parts:</b>        | 144                                                                                                                                                                          | TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                 |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLR2333P)                                                                                                                                    |                                                                   |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                   |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                   |

**Recommended Parts**

| No.                      | Qty | Part No. | Particulars                  | Condition | Repairer's       | Amount           |
|--------------------------|-----|----------|------------------------------|-----------|------------------|------------------|
| 1                        | 1   |          | <b>*TOTAL PART</b>           | 12820     | 16,044.00 F      | *16,044.00 F     |
| <b>Supplementary #1</b>  |     |          |                              |           |                  |                  |
| 2                        | 1   |          | <b>*AIR INT GRILLE ACTIV</b> |           | 240.00 F         | *240.00 F        |
| 3                        | 1   |          | <b>*COND/EVAPORATOR PIPE</b> |           | 310.00 F         | *310.00 F        |
| 4                        | 1   |          | <b>*FRT LWR BUMPER REINF</b> |           | 205.00 F         | *205.00 F        |
| 5                        | 1   |          | <b>*HEADLAMP MODULE RH</b>   |           | 350.00 F         | *350.00 F        |
| 6                        | 1   |          | <b>*L/LWR RADIATOR HOSE</b>  |           | 120.00 F         | *120.00 F        |
| 7                        | 1   |          | <b>*L/R STABI ROD</b>        |           | 60.00 F          | *60.00 F         |
| 8                        | 1   |          | <b>*LEVELLING SYS SENSOR</b> |           | 335.00 F         | *335.00 F        |
| 9                        | 1   |          | <b>*LWR FRT PNL C-MEMBER</b> |           | 185.00 F         | *185.00 F        |
| 10                       | 1   |          | <b>*R/F ABS SENSOR</b>       |           | 162.00 F         | *162.00 F        |
| 11                       | 1   |          | <b>*R/F PANEL SUPPORT</b>    |           | 90.00 F          | *90.00 F         |
| 12                       | 1   |          | <b>*R/F UPPER WING SEAL</b>  |           | 22.00 F          | *22.00 F         |
| 13                       | 1   |          | <b>*R/RADIATOR BRACKET</b>   |           | 36.00 F          | *36.00 F         |
| 14                       | 1   |          | <b>*R/R STABI ROD</b>        |           | 60.00 F          | *60.00 F         |
| 15                       | 1   |          | <b>*REAR AXLE SUBFRAME</b>   |           | 1,080.00 F       | *1,080.00 F      |
| <b>Total Parts (S\$)</b> |     |          |                              |           | <b>19,299.00</b> | <b>19,299.00</b> |

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items  
**There are no new miscellaneous items selected.**

## Recommended Labour

| No                      | Particulars                   | Lab.Type | Repairer's | Amount   |
|-------------------------|-------------------------------|----------|------------|----------|
| <u>Paintwork Labour</u> |                               |          |            |          |
| 1                       | Total Paint Labour            | New      | 361.20     | 361.20   |
| 2                       | Total Paint Materials         | New      | 197.02     | 197.02   |
| <u>Labour Items</u>     |                               |          |            |          |
| 3                       | Total Panel/Mechanical Labour | New      | 982.80     | 982.80   |
| Gross Labour Cost (S\$) |                               |          | 1,541.02   | 1,541.02 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >