

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21006149/KTCE2

Date: 15/07/2021

REFERENCE

Insured/Claimant:	AUTOBAHN RENT A CAR PTE LTD	Policy No:	DMHCSNA00004192100	Claim No:	SNM21D202944/C01/LEWLC
Date of Loss:	18/05/2021	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR2333P	Engine No:	2ZR6860386
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	ZVW506046773
Reg. Date:	04/08/2017 (Man. Year: 2016)	Odometer:	166146 km
Colour:	Metallic Silver		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 3 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,299.00	16,075.00	3,224.00	16.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	982.80	882.00	100.80	10.26
Paintwork Labour	558.22	462.36	95.86	17.17
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,840.02	17,419.36	3,420.66	16.41
Approved Total (Overridden) (S\$)		14,250.00		
- Excess (S\$)	0.00	2,000.00	-2,000.00	
(S\$)	20,840.02	12,250.00	8,590.02	41.22
+ GST 7.00/7.00% (S\$)	1,458.80	857.50	601.30	41.22
Nett Amount (S\$)	22,298.82	13,107.50	9,191.32	41.22

INSPECTION

Date of Assignment:	25/05/2021	Present Location:	Ding Auto Pte Ltd (HQ)
Date Inspected:	27/05/2021	Inspected At:	Ding Auto Pte Ltd (HQ) 176 Sin Ming Drive #04-06, Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	10.0 days		

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jul 2021)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR2333P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PART		16,044.00 F	*12,820.00 F
<u>Supplementary #1</u>						
2	1		*AIR INT GRILLE ACTIV	Cracked	240.00 F	*240.00 F
3	1		*COND/EVAPORATOR PIPE	Bent	310.00 F	*310.00 F
4	1		*FRT LWR BUMPER REINF	Bent	205.00 F	*205.00 F
5	1		*HEADLAMP MODULE RH	Cracked	350.00 F	*350.00 F
6	1		*L/LWR RADIATOR HOSE	Cut	120.00 F	*120.00 F
7	1		*L/R STABI ROD	Bent	60.00 F	*60.00 F
8	1		*LEVELLING SYS SENSOR	Cracked	335.00 F	*335.00 F
9	1		*LWR FRT PNL C-MEMBER	Bent	185.00 F	*185.00 F
10	1		*R/F ABS SENSOR	Shorted	162.00 F	*162.00 F
11	1		*R/F PANEL SUPPORT	Bent	90.00 F	*90.00 F
12	1		*R/F UPPER WING SEAL	Necessary	22.00 F	*22.00 F
13	1		*R/RADIATOR BRACKET	Distorted	36.00 F	*36.00 F
14	1		*R/R STABI ROD	Distorted	60.00 F	*60.00 F
15	1		*REAR AXLE SUBFRAME	Bent	1,080.00 F	*1,080.00 F
					Total Parts (S\$)	19,299.00
						16,075.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Labour	New	361.20	306.60
2	Total Paint Materials	New	197.02	155.76
Labour Items				
3	Total Panel/Mechanical Labour	New	982.80	882.00
Gross Labour Cost (\$\$)			1,541.02	1,344.36

Report was unsubmitted during this print-out.

< END OF ESTIMATES >