

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006151/AUCN2**Date:** 20/12/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00075442000

**Claimant Vehicle
No :** SJA7391B**Insured
Vehicle No :** GZ7547Z

Date of Loss: 22/05/2021

Nature of Claim: TP

Claim
No: SNM21D202975/C02/TOHHS**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SJA7391B**

Make & Model: MITSUBISHI COLT, RALLIART VERSION R 1.5 (A)

Engine No: 4G15JM3238

Reg. Date: 19/12/2007 (Man. Year: 2007)

Chassis No: Z27A0500116

Colour: Blue

Odometer: 317076 km

Engine Capacity: 1468 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45R16

Rear Tyre Size: 205/45R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,940.20	4,612.00	16,328.20	77.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,500.00	890.00	2,610.00	74.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	24,440.20	5,502.00	18,938.20	77.49
Approved Total (Overridden) (\$\$)		4,400.00		
Nett Amount (\$\$)	24,440.20	4,400.00	20,040.20	82.00

INSPECTION

Date of Assignment: 26/05/2021

Date Inspected: 27/05/2021 Inspected At:

8 KAKI BUKIT AVE 4
#01-51 PREMIER @KAKI BUKIT
REPAIRER: 1ST AUTO PRO PTE LTD

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Dec 2021)

Parts: 144 MITSUBISHI COLT RALLIART VERSION R 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJA7391B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	361.00 FL	*- FL
2	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	256.00 FL	*- FL
3	2		*FRONT BUMPER BRACKET LH/RH	Not Necessary	250.00 FL	*- FL
4	2		*FRONT BUMPER STAY LH/RH	Not Necessary	252.00 FL	*- FL
5	1		*FRONT BUMPER TOWING COVER	Not Necessary	116.00 FL	*- FL
6	2		*FRONT FOG LAMP LH/RH	Not Necessary	792.00 FL	*- FL
7	2		*FRONT FOG LAMP COVER LH/RH	Not Necessary	312.00 FL	*- FL
8	2		*BONNET HINGE LH/RH	Not Necessary	308.00 FL	*- FL
9	1		*BONNET RUBBER	Not Necessary	152.00 FL	*- FL
10	1		*BONNET LOCK	Not Necessary	155.00 FL	*- FL
11	1		*BONNET LOCK CATCH	Not Necessary	140.00 FL	*- FL
12	1		*BONNET LOCK CABLE	Not Necessary	125.00 FL	*- FL
13	1		*BONNET INSULATOR	Not Necessary	178.00 FL	*- FL
14	1		*BONNET STAND	Not Necessary	130.00 FL	*- FL
15	1		*FRONT GRILLE	Damaged	364.00 FL	*364.00 FL
16	1		*FRONT GRILLE LOGO	Necessary	142.00 FL	*55.00 FL
17	1		*FRONT SUPPORT PANEL	Repair	533.00 FL	*- FL
18	1		*FRONT SUPPORT PANEL LOWER GARNISH	Not Necessary	546.00 FL	*- FL
19	1		*FRONT BRACE PANEL	Bent	177.00 FL	*177.00 FL
20	2		*FRONT HEADLAMP LH/RH	Cracked	1,584.00 FL	*1,584.00 FL
21	2		*FRONT HEADLAMP BRACKET LH/RH	Not Necessary	252.00 FL	*- FL
22	2		*FRONT HEADLAMP PANEL LH/RH	Not Necessary	288.00 FL	*- FL
23	2		*RADIATOR TOP BRACKET LH/RH	Not Necessary	236.00 FL	*- FL
24	2		*RADIATOR BOTTOM BRACKET LH/RH	Not Necessary	236.00 FL	*- FL
25	1		*RADIATOR FAN	Not Necessary	165.00 FL	*- FL
26	1		*RADIATOR FAN COWLING	Not Necessary	227.00 FL	*- FL
27	1		*RADIATOR FAN MOTOR	Not Necessary	514.00 FL	*- FL
28	1		*RADIATOR FAN BLADE	Not Necessary	153.00 FL	*- FL
29	1		*RADIATOR TOP HOSE	Not Necessary	115.00 FL	*- FL
30	1		*RADIATOR BOTTOM HOSE	Not Necessary	138.00 FL	*- FL
31	2		*RADIATOR AIR GUIDE LH/RH	Not Necessary	236.00 FL	*- FL
32	1		*RADIATOR LOWER CROSS MEMBER	Not Necessary	381.00 FL	*- FL
33	1		*AIR CON CONDENSER	Not Necessary	1,054.00 FL	*- FL
34	2		*AIR CON CONDENSER BRACKET LH/RH	Not Necessary	236.00 FL	*- FL
35	1		*AIR CON SUCTION PIPE	Not Necessary	317.00 FL	*- FL
36	1		*AIR CON RETURN PIPE	Not Necessary	261.00 FL	*- FL
37	1		*AIR CON DISCHARGE PIPE	Not Necessary	271.00 FL	*- FL
38	1		*AIR CON COMPRESSOR	Not Necessary	1,071.00 FL	*- FL
39	1		*FRONT CHASSIS FRAME RH	Not Necessary	1,550.00 FL	*- FL
40	2		*FRONT CHASSIS MEMBER LH/RH	Not Necessary	1,404.00 FL	*- FL
41	1		*FRONT GRILLE CLIPS	Necessary	80.00 FS	*20.00 FS
42	1		*FRONT NUMBER PLATE	Not Necessary	100.00 FS	*- FS
43	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
44	1		*BONNET-CARBON FIBRE AFTERMARKET	Dented	1,500.00 FS	*900.00 FS
45	1		*FRONT BUMPER-AFTERMARKET	Deformed	1,500.00 FS	*800.00 FS
46	1		*FRONT BUMPER GUARD-AFTERMARKET	Not Necessary	300.00 FS	*- FS

Report was unsubmitted during this print-out.

12/20/21, 2:08 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*RADIATOR-AFTERMARKET	Not Necessary	1,500.00 FS	*- FS
48	1		*INTERCOOLER-AFTERMARKET	Dented	1,500.00 FS	*900.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					22,538.00	4,830.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					1,597.80	218.00
Total Parts (\$\$)					20,940.20	4,612.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIT AND TRANSFER FRONT BUMPER COMPONENT	New	150.00	0.00
2	TO REMOVE AND REFIT ELECTRICAL WIRING,REPLACE DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING-FRONT	New	150.00	30.00
3	TO REMOVE AND REFIT INNER TRIMS AND GARNISHES TO FACILITATE THE REPAIR-FRONT	New	150.00	0.00
4	TO TOP UP AIRCON GAS + COOLANT	New	200.00	0.00
5	TO APPLY UNDERCOATING ON REPLACED AND REPAIRED PANELS FOR RUST PROTECTION	New	100.00	0.00
6	TO PROVIDE SPRAY PAINTING ON THE REPLACED AND REPAIRED PARTS	New	1,000.00	400.00
7	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO ORIGINAL POAITION USING POWER TOOLS	New	1,500.00	400.00
8	TO REMOVE AND REFIT RADIATOR + CONDENSER + COMPRESSOR + INTERCOOLER	New	250.00	60.00
Gross Labour Cost (\$\$)			3,500.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >