

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006153/BGS3Q2**Date:** 07/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100402147
Claimant Vehicle No :	SKT9324X	Insured Vehicle No :	SKR4483M
Date of Loss:	25/05/2021	Nature of Claim:	TP
		Claim No:	8059118779SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT9324X	Engine No:	R18A12804291
Make & Model:	HONDA STREAM, 1.7 (A)	Chassis No:	JHMRN68408S204290
Reg. Date:	14/08/2008 (Man. Year: 2008)	Odometer:	227511 km
Colour:	Silver		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,364.06	2,652.48	4,711.58	63.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	1,430.00	1,650.00	53.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,444.06	4,082.48	6,361.58	60.91
Approved Total (Overridden) (S\$)		3,250.00		
(S\$)	10,444.06	3,250.00	7,194.06	68.88
+ GST 7.00/7.00% (S\$)	731.08	227.50	503.58	68.88
Nett Amount (S\$)	11,175.14	3,477.50	7,697.64	68.88
+ Car Rental (6.0 x S\$120.00/day + 7.00% GST) (S\$)		770.40		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,255.35		
Global Sum Settlement (S\$)		4,200.00		

INSPECTION

Date of Assignment:	27/05/2021	Team Autopro Pte Ltd - Sin Ming (HQ)
Date Inspected:	27/05/2021 Inspected At:	160 SIN MING DRIVE #02-12 SIN MING
		AUTOCITY
		Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,270.00 FL	*903.20 FL
2	1		*TAILGATE LOGO	Necessary	78.00 FL	*29.90 FL
3	1		*TAILGATE WINDSCREEN MOULDING	Necessary	129.00 FL	*92.80 FL
4	1		*TAILGATE INNER TRIM BOARD	Broken	366.50 FL	*366.50 FL
5	1		*TAILGATE INNER LOCK	Jammed	187.60 FL	*109.50 FL
6	1		*TAILGATE INNER LOCK STRIKER	Not Damaged	41.08 FL	*- FL
7	1		*TAILGATE WEATHERSTRIP	Torn	245.00 FL	*116.90 FL
8	1		*REAR BUMPER	Broken	987.60 FL	*665.40 FL
9	2		*REAR BUMPER SIDE RETAINER	Necessary	237.20 FL	*51.00 FL
10	2		*REAR BUMPER BRACKET	No such part	244.00 FL	*- FL
11	1		*REAR BUMPER TOW CAP	Not Damaged	105.60 FL	*- FL
12	1		*REAR END PANEL	Repair	980.60 FL	*- FL
13	1		*REAR END PANEL TOP GARNISH	Broken	117.80 FL	*117.80 FL
14	1		*REAR FENDER INNER TRIM BOARD LH	Not Damaged	458.40 FL	*- FL
15	2		*TAILLAMP	Not Damaged	1,251.80 FL	*- FL
16	1		*REAR EXHAUST PIPE TIP	Dented	180.00 FL	*148.00 FL
17	1		*TAILGATE SEALANT	Not Necessary	100.00 FS	*- FS
18	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
19	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
20	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*60.00 FS
21	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
22	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
23	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
24	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
25	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
26	2		*TAILLAMP SEAL	Not Necessary	120.00 FS	*- FS
27	1		*SPARE TYRE BRACKET	Bent	276.70 FL	*121.60 FL
28	1		*SPARE TYRE BRACKET FASTENER	Missing	98.20 FL	*68.00 FL
29	4		*REAR BUMPER REVERSE SENSOR	Scratched	800.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,815.08	3,210.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,451.02	558.12
Total Parts (\$\$)	7,364.06	2,652.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	CHECK WIRING	New	100.00	0.00
4	UPHOLSTERY	New	300.00	0.00
5	PANEL BEATING	New	1,000.00	600.00
6	RUST PROOFING	New	200.00	0.00
7	SPRAY PAINTING	New	1,000.00	600.00
8	R&R SPARE TYRE BRACKET	New	80.00	30.00
Gross Labour Cost (\$\$)			3,080.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >