

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21006167/T1TF3E2

**Date:** 24/09/2021

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 30001726040

**Claimant Vehicle No :** SG5853K

**Insured Vehicle No :** GBE5766R

Date of Loss: 29/04/2021

Nature of Claim: TP

Claim No: 256722

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SG5853K**

Make & Model: MAN A95, 10.5 D (A)

Engine No: 50344742574477

Reg. Date: 22/09/2017 (Man. Year: 2016)

Chassis No: WMAA95ZZ9G7003525

Colour: Green

Odometer: 164395 km

Engine Capacity: 10518 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 8/8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 8/8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,066.00	2,572.00	1,494.00	36.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,392.00	2,200.00	192.00	8.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,458.00</b>	<b>4,772.00</b>	<b>1,686.00</b>	<b>26.11</b>
<b>+ GST 7.00/7.00% (S\$)</b>	452.06	334.04	118.02	26.11
<b>Nett Amount (S\$)</b>	<b>6,910.06</b>	<b>5,106.04</b>	<b>1,804.02</b>	<b>26.11</b>

### INSPECTION

Date of Assignment: 27/05/2021

Date Inspected: 31/05/2021

Inspected At:

SBS Transit Ltd (Defu)

4 Defu Ave 1

Singapore 539536

Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 24 Sep 2021)	
<b>Parts:</b>	N/A	MAN A95 10.5 D (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SG5853K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REFLECTOR	Cracked	12.00 F	*12.00 F
2	1		*ENGINE DOOR.RR.FRP	Repair	747.00 F	*- F
3	1		*COVER.FRP HEADLAMP.REAR N/S	Cracked	390.00 F	*390.00 F
4	1		*STICKER REFLECTOR.RIGHT.LTA 122 BATCH 1	Necessary	55.00 F	*55.00 F
5	1		*LAMP.LED.CENTRE BRAKE.2BA 959 071-777	Cracked	110.00 F	*110.00 F
6	1		*STICKER REFLECTOR.LEFT.LTA 122 BATCH 1	Necessary	55.00 F	*55.00 F
7	1		*ENGINE DOOR.RR.ERP	Repeated	747.00 F	*- F
8	1		*ENGINE DOOR.RR.COMPLETE.A95.E5	Bent	1,500.00 F	*1,500.00 F
9	1		*LAMP.REVERSE.(BULB)	Cracked	98.00 F	*98.00 F
10	1		*LED.TAIL/STOP LAMP.RR.LH/RH	Cracked	104.00 F	*104.00 F
11	1		*LAMP HSG W/OUT BULB.FOG.RR	Cracked	98.00 F	*98.00 F
12	1		*LED.SIGNAL LAMP.RR.LH/RH	Cracked	150.00 F	*150.00 F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>4,066.00</b>	<b>2,572.00</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	(2) WORKSHOP LABOUR	New	192.00	0.00
2	CONTRACTORS REPAIR CHARGES	New	2,200.00	2,200.00
<b>Gross Labour Cost (S\$)</b>			<b>2,392.00</b>	<b>2,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >