

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006171/KPA3Q2
Date: 23/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100409143
Claimant Vehicle No :	GBK569U	Insured Vehicle No :	SKS4240S
Date of Loss:	26/05/2021	Nature of Claim:	TP
		Claim No:	8216215546SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK569U		
Make & Model:	NISSAN NV200, 1.5 (M)	Engine No:	K9KE628D705963
Reg. Date:	02/12/2019 (Man. Year: 2019)	Chassis No:	VSKYBAM20U0179952
Colour:	White	Odometer:	18344 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Goodyear 9 mm	Rear Left Side:	Goodyear 9 mm
Front Right Side:	Goodyear 9 mm	Rear Right Side:	Goodyear 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,985.77	3,054.13	2,931.64	48.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,550.00	1,820.00	3,730.00	67.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	11,535.77	4,874.13	6,661.64	57.75
	+ Loss of Use (8.0 x S\$60.00/day) (S\$)	480.00		
	+ Doc/Search Fee (S\$)	7.45		

Nett Liability (S\$)	5,361.58
Global Sum Settlement (S\$)	5,300.00

INSPECTION

Date of Assignment: 27/05/2021

Date Inspected: 28/05/2021

Estimated Period of Repair: 7.0 days

Inspected At:

Caris Autoworks Pte Ltd (HQ)
160 SIN MING DRIVE
#05-03 SIN MING AUTOCITY
SINGAPORE 575722

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR ASSY (FRONT RIGHT)	Bent	1,229.70 FL	*1,219.70 FL
2	1		*BODY SIDE PANEL (FRONT RIGHT)	Bent	1,355.90 FL	*807.90 FL
3	2		*DOOR HINGE (FRONT RIGHT)	Repair	130.20 FL	*- FL
4	1		*DOOR LOCK (FRONT RIGHT)	Repair	176.50 FL	*- FL
5	1		*DOOR LOCK STOPPER (FRONT RIGHT)	Serviceable	48.90 FL	*- FL
6	2		*DOOR BOLT (FRONT RIGHT)	Not Necessary	36.40 FL	*- FL
7	1		*DOOR HANDLE (FRONT RIGHT)	Serviceable	74.20 FL	*- FL
8	1		*DOOR WEATHERSTRIP (FRONT RIGHT)	Torn	89.90 FL	*89.90 FL
9	1		*DOOR MOULDING OUTER (FRONT RIGHT)	Serviceable	93.10 FL	*- FL
10	1		*POWER WINDOW REGULATOR (FRONT RIGHT)	Distorted	93.90 FL	*93.90 FL
11	1		*POWER WINDOW MOTOR (FRONT RIGHT)	Jammed	527.10 FL	*254.10 FL
12	1		*PETROL COVER (FRONT RIGHT)	Repair	129.60 FL	*- FL
13	1		*MANGUARD (FRONT RIGHT)	Bent	504.70 FL	*504.70 FL
14	1		*MANGUARD (REAR RIGHT)	Repair	1,709.70 FL	*- FL
15	1		*BRAKE LAMP (REAR RIGHT)	Cut	258.70 FL	*258.70 FL
16	1		*SET RIM COVER	Dented	136.80 FL	*136.80 FL
17	1		*COMPANY STICKERS	Necessary	50.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,645.30	3,390.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	659.53	336.57
Total Parts (\$\$)	5,985.77	3,054.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL KNOCKING	New	2,600.00	800.00
2	SPRAY PAINTING	New	2,200.00	900.00
3	BODY CLIPS	New	100.00	0.00
4	WHEEL ALIGNMENT	New	120.00	60.00
5	LABOUR CHARGE TO CHARGE POWER WINDOW REGULATOR (FRONT RIGHT) }	New	180.00	60.00
6	LABOUR TO REPLACE NEW DOOR (FRONT RIGHT) }	New	350.00	0.00
Gross Labour Cost (\$)			5,550.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >