#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21006173/AGQF3E2

08/10/2021 Date:

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001490128

**Claimant Vehicle** SJY9945P Insured Vehicle No: SJH5970G No:

Date of Loss: 26/05/2021 Nature of Claim: TP Claim No: 257901

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SJY9945P** 

Make & Model: VOLKSWAGEN NEW GOLF, 1.4 AT 5K13G5 (A) CAX542590 **Engine No:** 

Reg. Date: 21/10/2010 (Man. Year: 2010) Chassis No: WVWZZZ1KZAW396240

Colour: Odometer: 185677 km Grey

**Engine Capacity:** 1390 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18 Front Left Side: Rear Left Side: Falken 6 mm Falken 6 mm Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,394.00	5,094.00	2,300.00	31.11
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,500.00	1,350.00	1,150.00	46.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	9,894.00	6,444.00	3,450.00	34.87
	Approved Total (Overridden) (S\$)		5,100.00		
	Nett Amount (S\$)	9,894.00	5,100.00	4,794.00	48.45

**INSPECTION** 

Date of Assignment: 27/05/2021

Date Inspected: 27/05/2021 Inspected At:

10 Kaki Bukit Road 2 #03-01, First East Centre,

ADVANCE AUTO GARAGE (#03-01) (HQ)

Singapore 417868

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Oct 2021)

Parts: 144 VOLKSWAGEN NEW GOLF 1.4 AT 5K13G5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJY9945P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*-FS
2	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*FRONT BUMPER	Deformed	969.00 F	*969.00 FL
4	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
5	2		*FRONT BUMPER SIDE HOLDER	Not Necessary	116.00 F	*- FL
6	1		*FRONT BUMPER SPONGE	N/S Cracked	182.00 F	*91.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Dented	597.00 F	*597.00 FL
8	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	207.00 F	*- FL
9	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	310.00 F	*- FL
10	1		*FRONT BUMPER FOG LAMP GRILLE LH	Not Necessary	78.00 F	*- FL
11	1		*FRONT GRILLE	Cracked	317.00 F	*317.00 FL
12	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
13	1		*FRONT GRILLE LOGO	Necessary	78.00 F	*78.00 FL
14	1		*HEADLAMP LH	Cracked	931.00 F	*931.00 FL
15	1		*HEADLAMP TOP PANEL LH	Buckled	165.00 F	*165.00 FL
16	1		*HEADLAMP LOWER BRACKET LH	Cracked	48.00 F	*48.00 FL
17	1		*FRONT SUPPORT PANEL	Cracked	840.00 F	*840.00 FL
18	1		*AIR CON CONDENSER	Bent	685.00 F	*685.00 FL
19	1		*RADIATOR	Not Necessary	587.00 F	*- FL
20	1		*BONNET	Buckled	839.00 F	*839.00 FL
21	1		*BONNET LOCK	Not Necessary	75.00 F	*- FL
22	1		*COOLANT	Necessary	60.00 FS	*40.00 FS
23	1		*AIR FILTER	Not Necessary	180.00 FS	*-FS
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	7,394.00	5,650.00
			- List Item Discount on L It	ems 0.00/10.00% (S\$)	0.00	556.00
				Total Parts (S\$)	7,394.00	5,094.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	1,400.00	700.00
2	SPRAY PAINTING	New	800.00	500.00
3	WIRING	New	100.00	30.00
4	TO REMOVE CONDENSER AND TOP UP AIR CON GAS	New	100.00	60.00
5	TO REMOVE RADIATOR AND TO TOP UP COOLANT	New	100.00	60.00
		Gross Labour Cost (S\$)	2,500.00	1,350.00
	Report was unsubmit	tted during this print-out.		

< END OF ESTIMATES >