

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006179/NRA3Q2
Date: 17/12/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070144967
Claimant Vehicle No :	SH8611S	Insured Vehicle No :	SMV7759D
Date of Loss:	24/05/2021	Nature of Claim:	TP
		Claim No:	0754221038SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8611S	Engine No:	G4LEKU422008
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVLU192945
Reg. Date:	29/04/2021 (Man. Year: 2019)	Odometer:	5407 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,699.00	787.12	2,911.88	78.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	1,200.00	300.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,199.00	1,987.12	3,211.88	61.78
+ GST 7.00/7.00% (S\$)	363.93	139.10	224.83	61.78

Nett Amount (S\$)	5,562.93	2,126.22	3,436.71	61.78
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$125.19/day) (S\$)		500.76		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,828.98		

INSPECTION

Date of Assignment: 27/05/2021

Date Inspected: 27/05/2021

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Repair	430.90 FL	*- FL
2	1		*FRONT BUMPER BRACKET RH	Serviceable	35.00 FL	*- FL
3	1		*FRONT HEADLAMP ASSY RH	Serviceable	1,993.65 FL	*- FL
4	1		*FRONT FENDER RH	Dented	588.80 FL	*588.80 FL
5	1		*FRONT FENDER SHIELD RH	Serviceable	164.70 FL	*- FL
6	1		*FRONT FENDER ENBLEM	Necessary	26.60 FL	*26.60 FL
7	1		*FRONT BUMPER GRILLE RH	Serviceable	186.90 FL	*- FL
8	1		*FRONT DOOR PROTECTOR RH	Serviceable	186.20 FL	*- FL
9	1		*FRONT DAY LIGHT RH	Serviceable	642.50 FL	*- FL
10	1		*FRONT WHEEL COVER RH	Scratched	368.50 FL	*368.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,623.75	983.90
- List Item Discount on L Items 20.00/20.00% (S\$)	924.75	196.78
Total Parts (S\$)	3,699.00	787.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	750.00	700.00
2	SPRAY PAINT	New	600.00	500.00
3	RESET FRONT WHEEL ALIGNMENT	New	90.00	0.00
4	CHECK LIGHTING	New	60.00	0.00
Gross Labour Cost (\$)			1,500.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >