

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559H GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 58530
Date Estimated : 27/05/2021
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJT8327G	WBA4N32090K541065	22/09/2016	420iA/2	50535

DESCRIPTION	QTY	PRIC	VALUE
TAIL END PANEL <i>bt / photo?</i>	1	598.15	598.15
BOOTLID <i>bt</i>	1	1,247.30	1,247.30
WASHER GASKET (carrier) <i>? xan</i>	2	4.20	8.40
RR BUMPER CARRIER ECE <i>? bt</i>	1	470.25	470.25
REINFORCEMENT BUMPER REAR BOTTOM <i>? can</i>	1	63.55	63.55
REAR BUMPER TRIM STRIP (SPORT LINE) <i>sur</i>	1	82.85	82.85
REAR BUMPER CENTRE GUIDE <i>? can</i>	1	56.05	56.05
RR LH RETAINING STRIP FOR TRIM STRI <i>? cut</i>	1	12.65	12.65
RR RH RETAINING STRIP FOR TRIM STRI <i>? cut</i>	1	12.05	12.05
REAR BUMPER PRIMED PANEL (ZWEIF/LIN) <i>de</i>	1	1,220.30	1,220.30
RR BUMPER LH SIDE GUIDE <i>? xsur</i>	1	56.05	56.05
LETTERING 420i <i>sur</i>	1	64.75	64.75
GROMMET <i>sur</i>	2	0.80	1.60
PLAQUE 74MM <i>sur</i>	1	71.95	71.95
PLUG BLACK D=5MM <i>? sur</i>	7	0.95	6.65
SENSOR WIRE FOR SMART OPENER TOP <i>? xan</i>	1	46.55	46.55
SENSOR WIRE FOR SMART OPENER BOTTOM <i>? xan</i>	1	51.20	51.20
DECOUPLING RING PDC TORQUE CONVERTE <i>sur</i>	1	5.15	5.15
PDC SENSOR MELBOURNEROT (A75) <i>sur</i>	1	371.20	371.20
BLIND RIVET AVIBVLB <i>sur</i>	25	0.55	13.75
SCREW (SF PLUS M5X15) <i>sur</i>	6	0.55	3.30
(DG/SL) BODY ADHESIVE K5B (195ML) <i>sur</i>	1	336.75	336.75
PUNCH RIVET N5 <i>sur</i>	12	0.55	6.60
(DG) CLEANER R1 (100ML) <i>sur</i>	1	26.15	26.15
PUNCH RIVET N4 <i>sur</i>	13	0.55	7.15
(S/L) SEAM SEAL 300ML <i>sur</i>	1	33.80	33.80

5,195.56

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 01/06/21 @ 12:10 Excess S\$ _____

Surveyor's Name Rafael Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 10 days

Total Parts
LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____ : 11,917.00

Labour 1 : 11,917.00

Parts : 5,195.56

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 1,197.88

Grand Total : 18,310.44



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401555W GST Reg. No M2-0020081-X
Toll-Free Number (1800-3255149)

315, Alexandra Road
Sime Darby Performance Centre
Singapore 159944
Fax: 64796601

385, Kampong Arang Road
East Coast Centre
Singapore 418180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 58530
Date Estimated : 27/05/2021
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lynette Lee Bee Leng
6 Peach Garden
#13-08

Singapore 437606

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJT8327G	WBA4N32090K541065	22/09/2016	420iA/2	50535

DESCRIPTION

To replace rear bumper, boot lid, tail panel and attachments.

To painting rear bumper, boot lid, tail panel and trunk floor.

To check electrical wiring system and lighting at the rear section for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

To remove and install boot compartment carpet and garnish to facilitate repair.

To replace bootlid smart opener control unit, top and bottom sensor line including program and conduct check for proper function.

To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.

To carry out body cavity preservation.
(Per panel).

To carry out body cavity preservation.
(For cut panel).

Sundries.

VALUE

5100 5,980.00

3183 3,351.00

168 177.00

168 177.00

257 271.00

Xnn 628? 661.00

504 531.00

112 118.00

504 531.00

150.00

Total Labour 1: 11,917.00

DESCRIPTION

Insulation e ? Xnn

TAILPIPE TIP BLACK CHROME (SPORT) repair

QTY

PRIC

VALUE

3 25.80

77.40

2 125.25

250.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



supplementary

Estimate No. : **b1 58530**
Date Estimated : **27/05/2021**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Lynette Lee Bee Leng
6 Peach Garden
#13-08

Singapore 437606

- ACCOUNT - 158
Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJT8327G	WBA4N32090K5410	22/09/2016	420iA/2	51595

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT ✓ nec	1.00	2.00	0.00	2.00
# WASHER GASKET ✓ nec	4.20	2.00	0.00	8.40
# REAR PDC HOLDER SET (PDC & PMA) ✓ nec	67.65	1.00	0.00	67.65
# (DG) BODYWORK ADHESIVE K5A (50ML) ✓ nec	116.15	1.00	0.00	116.15
# (DG/SL) ADHESIVE SET K6 ✓ nec	53.05	1.00	0.00	53.05

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	247.25