

PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers
Blk 779 #01-1545 Yishun Ave 2 Singapore 760779
Tel: 62934822 Fax: 62963283
E-mail: admin@priorityservices.sg

Date:

28 January 2021

Your Ref:

CMTD1802664/THE

Our Ref:

TP-0118/12/18

Motor Claims Department M/s. Sompo Insurance Pte. Ltd. 50 Raffles Place #05-01/06 Singapore Land Tower Singapore 048623

Attention: Ms. Thelma Choo

Madam,

Inspection of 2016 Honda Mobilio (A)

Registration No.: SLF 2344 X Odometer Reading: 44528 km

Chassis No.: MRHDD4870GP000231

We refer to your instructions to us to conduct a paper survey of the above vehicle. A prerepair survey was conducted on 27-06-2018, followed by inspection of dismantled parts on 28-06-2018 and resurvey after repairs on 02-07-2018.

The following documents were received: -

- 1) Copy of survey report by M/s. C L Appraiser Pte Ltd
- 2) 88 copies of photos depicting damages sustained by SLF 2344 X
- 3) Accident reports by drivers of SLF 2344 X and SLB 1740 M

The vehicle sustained rear damages during an accident on 22-06-2018.

Repair cost submitted was \$8,300.00 lump-sum.

We append below our findings: -

Replacement of Parts		Revised Amount		Our Recommendation	
1pc.	Rear windscreen moulding – 50% on pre-existing damages	\$	118.50	\$	59.25
lpc.	Rear tail gate – 50% on pre-existing damages		1,285.00		642.50
lpc.	Rear tail gate inner lock - no evidence	e \$	303.20	\$	-

	of domago				
2naa	of damage Rear tail gate lamps – refitted		766.40		
2pcs. 1pc.	Rear tail gate inner trim board –		489.50		-
ipe.	refitted		707,50		-
	Total				
1pc.	Rear tail gate inner pull pocket –		82.60		_
•	refitted				
lpc.	Rear tail gate weatherstrip – intact		189.60		-
1pc.	Rear tail gate HONDA emblem – 50%		43.00		21.50
	on pre-existing damages				
1pc.	Rear tail gate MOBILIO emblem –		68.50		34.25
	50% on pre-existing damages				
1 pc .	Rear tail gate i-VTEC emblem – 50%		23.50		11.75
	on pre-existing damages				
lpc.	Rear tail gate RS emblem – 50% on		85.00		42.50
	pre-existing damages				
2pcs.	Rear number plate lamps – not affected		97.00		_
lpc.	Rear tail gate outer garnish – not		185.00		-
2	affected		1 171 00		
2pcs.	Rear tail lamps – refitted		1,171.80		-
lpc.	Rear end panel – repairable		685.00		_
lpc.	Rear end panel inner garnish – refitted		212.60		1 195 00
lpc.	Rear bumper inner spanses		1,185.00 220.00		1,185.00
2pcs.	Rear bumper inner sponges – serviceable		220.00		-
1pc.	Rear bumper reflector – serviceable		68.00		_
2pcs.	Rear bumper side retainer –		97.00		_
	serviceable				
2pcs.	Rear bumper PDC sensors		390.00		280.00
lpc.	Rear bumper chrome moulding		285.00		285.00
1pc.	Rear exhaust silencer – refurbished		789.50		-
2pcs.	Rear exhaust mountings – not affected		57.00		-
		•			
	Y 2007	\$	8,897.70	\$	2,561.75
	Less 20%		1,779.54		512.35
		\$	7,118.16	\$	2,049.40
		Ψ	7,110.10	Ψ	2,047.40
Special	Nett Items:-				
lpc.	Rear windscreen sealant – 50% on pre-	\$	50.00	\$	25.00
	existing damages				
lset	Rear bumper clip		45.00		45.00
lpc.	Rear reverse camera – functional at		480.00		_
	time of PRS		105.00		10,700
lpc.	Rear exhaust chrome tail pipe		105.00		105.00
	Total Fou Douter	ሰ ጉ	7 700 16	φ	2 224 40
	Total For Parts:-	\$	7,798.16	\$	2,224.40
Labour	Charges:-				
To remo	ove, refit, replaced damaged lamps and	\$	50.00	\$	30.00

check up rear electrical wiring.

To remove and refit inner garnishes, inner trim to assist repair.		120.00	80.00	
To remove and refit rear reverse sensor and camera.		120.00	100.00	
To transfer rear tail gate mechanism and wiring assy to assist repair. – 50% on pre-existing damages		60.00	30.00	
To remove and refit rear windscreen glass. – 50% on pre-existing damages		150.00	60.00	
To remove, refit and replace exhaust silencer and mountings. – not necessary		120.00	-	
To apply undercoating on repaired and replaced panel.		90.00	60.00	
To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld, realign body structure and damaged consistent to the accident. – with contribution of \$100.00 for replacing tail gate		1,000.00	500.00	
To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident. – with contribution of \$100.00 for painting tail gate		880.00	500.00	
Total:-	\$	10,388.16	\$ 3,584.40	
Lump-sum repairs:	\$	8,300.00	\$ 2,850.00	

Estimated period of repairs: 4 working days

Pre-accident Market Value : About \$ 82,000.00 PARF/COE rebate : \$ 56,707.00

After viewing the video footage of the vehicle before and after the accident which we received from you on 20/01/2021. We noted that the tail gate has pre-existing dents prior to the accident impact. We recommend a 50% contribution to the replacement of the tail gate and its attachments.

Our initial recommendation of \$3,600.00 has been revised to \$2,850.00.

Vehicle within economical limit to repair.

We leave the decision of settlement to you.

Assuring you of our best services always

Yours faithfully PRIORITY SERVICES

JIMMY S.-P. LEE AMSOE, AMIRTE, MSAAA Motor Appraiser

Surveyed by:

LAWRENCE NG, MSAAA Motor Appraiser