



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 1240L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BENT	818.00	818.00
1	REAR BUMPER TOP BEAM	BENT	82.00	82.00
1	REAR BUMPER TOW COVER	SERVICEABLE	20.00	-
1	REAR BUMPER REINFORCEMENT	BENT	210.00	210.00
2	REAR BUMPER RETAINER @\$20.00	N/S CRACKED	40.00	20.00
1	REAR BUMPER REFLECTOR-LH	CRACKED	22.00	22.00
1	REAR FENDER-LH	TO REPAIR SEE LABOUR	898.00	-
1	REAR FENDER DUST COVER-LH	SERVICEABLE	30.00	-
9	REAR FENDER DUST COVER CLIPS @\$5.00	NOT NECESSARY	45.00	-
1	SET REAR LAMP	CRACKED	980.00	980.00
1	REAR LAMP PANEL-L/H	TO REPAIR SEE LABOUR	83.00	-
1	REAR END PANEL	BENT	506.00	506.00
1	REAR CHASSIS MEMBER	BENT	176.00	176.00
1	KEYLESS OPERATION SENSOR	SERVICEABLE	155.00	-
1	REAR SPARE TYRE BOARD	SERVICEABLE	160.00	-
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	521.00	-
1	REAR FENDER INNER GARNISH-LH	CRACKED	223.00	223.00
1	REAR LID	TO REPAIR SEE LABOUR	569.00	-
1	REAR LID LOCK	DENTED	65.00	65.00
	LESS 10% DISCOUNT		-560.30	-310.20
			5,042.70	2,791.80
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR REVERSE SENSOR (SN)	DENTED	280.00	200.00
1	REVERSE CAMERA (SN)	SHORTED	280.00	250.00
			560.00	450.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO PULL,KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART.INCLUSIVE OF THE REPAIR OF REAR FENDER-LH,REAR LAMP PANEL-L/H,REAR SPARE TYRE PANEL AND REAR LID.		1,200.00	900.00
	TO SPRAY PAINT ON REAR ACCIDENT PORTION.		1,500.00	1,100.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	180.00	-
	TO REMOVE AND REINSTALL FUEL TANK PIPING.	NOT NECESSARY	180.00	-
	TO DISMANTLE & REPLACE 1 SET REVERSE SENSOR.		120.00	50.00
	TO ANTI RUST AFFECTED AREAS.		80.00	30.00
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		80.00	20.00
			3,340.00	2,100.00
	GRAND TOTAL		8,942.70	5,341.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,250.00

Report Ref No. CS/AGI21006182/Kvf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.