

ASS. FEE BY:

REF:

CS/CTI 21006183/Dtc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKS 8172 D Yr Regn: 2015 MayType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C180 C.C. 1595Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 68538 T/Radio: Insured / Std / NI / NAEng/No: 27491030357307C/No: WDD2050402R055714Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/50 R17R: 11

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bridgestone

Front

Rear

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 25/05/221 D.O.I. 28/05/221Survey held at JWG AMKDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop orRear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>China Teiping GBL 1036 D</u>
<u>15/07/22</u>	<u>Phone L/S 95001 - with 6 days 2 hrs</u>
	<u>red: 34984.16; 78%</u>

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Task (\$

Days Of Repair: 6

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Photos

Report Format:

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: CHINA TAIPING INSURANCE SINGAPORE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING GBL1036D [YOUR INSURED] & SKS8172D [OUR CLIENT]
ON 25/05/2021.

ESTIMATED REPAIR COSTS FOR SKS8172D

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	BOOTLID <i>nt</i>	2170.00	\$ 2,927.00 ✓
1PC	BOOTLID LOGO <i>Hec</i>	59.80	\$ 84.00 ✓
1PC	BOOTLID 'C180' EMBLEM <i>Hec</i>		\$ 85.00 ✓
1PC	BOOTLID 'C&C' EMBLEM <i>Hec</i>	63.25	\$ 100.00 ✓
1PC	BOOTLID CENTER CHROME <i>HH</i>		\$ 236.00 X
2PC	BOOTLID NO. PLATE LAMP L+R @ \$30.00 EACH <i>HH</i>		\$ 60.00 X
1PC	BOOTLID INNER TRIM <i>HH</i>		\$ 263.00 X
1PC	BOOTLID WEATHER STRIP <i>SVC</i>		\$ 199.00 X
2PC	BOOTLID HINGE L+R @ \$174.00 EACH <i>HH</i>		\$ 348.00 X
1PC	BOOTLID LOCK <i>HH</i>		\$ 387.00 X
1PC	BOOTLID SWITCH <i>HH</i>		\$ 351.00 X
1PC	REAR WINDSCREEN MOULDING <i>HH</i>		\$ 384.00 X
1PC	REAR BUMPER <i>Dental</i>	1590.00	\$ 1,997.00 ✓
2PC	REAR BUMPER SIDE RETAINER L+R @ \$146.00 EACH <i>SVC</i>		\$ 292.00 X
1PC	REAR BUMPER CENTER BRACKET <i>HH</i>		\$ 330.00 X
2PC	REAR BUMPER SIDE BRACKET L+R @ \$153.00 EACH <i>HH</i>		\$ 306.00 X
2PC	REAR BUMPER CHROME MOULDING L+R @ \$398.00 EACH <i>HH NF</i>		\$ 796.00 X
1PC	REAR BUMPER TOW HOOK COVER <i>dislodged</i>		\$ 98.00 ✓
1PC	REAR BUMPER LOWER LID <i>authentic 1 Dental</i>	680.00	\$ 1,008.00 ✓
1PC	REAR BUMPER LOWER LID CHROME <i>made 1 Hec</i>	297.00	\$ 460.00 ✓
4PC	REAR BUMPER SENSOR @ \$321.00 EACH 2 pc <i>Dental 2 pc SVC</i>		\$ 1,284.00 ✓ 380.00
4PC	REAR BUMPER SENSOR HOLDER @ \$18.10 EACH <i>SVC</i>		\$ 72.40 X
1PC	REAR BUMPER SENSOR WIREHARNES <i>HH</i>		\$ 1,680.00 X
1PC	REAR REINFORCEMENT BAR <i>Dental</i>	684.00	\$ 1,106.00 ✓
1PC	REAR BUMPER TOW HOOK COVER <i>repaired</i>		\$ 79.00 X
2PC	TAIL LAMP L+R @ \$981.00 EACH 0 <i>S Hec H/S HH</i>	696.00	\$ 1,962.00 ✓
2PC	TAIL LAMP PANEL L+R @ \$679.00 EACH <i>HH</i>		\$ 1,358.00 X
2PC	TAIL LAMP LOWER BRACKET L+R @ \$184.00 EACH <i>HH</i>		\$ 368.00 X
2PC	REAR FENDER L+R @ \$2,394.00 EACH <i>HH</i>		\$ 4,788.00 X
2PC	REAR FENDER INNER TRIM L+R @ \$246.00 EACH <i>HH</i>		\$ 492.00 X

2PC	REAR FENDER INNER SHIELD L+R @ \$182.00 EACH	44	\$ 364.00	X
1PC	REAR END PANEL		\$ 2,158.00	X
1PC	REAR END PANEL TOP GARNISH	44	\$ 363.00	X
1PC	SPARE WHEEL PANEL	44	\$ 2,324.00	X
2PC	SPARE WHEEL QUARTER PANEL L+R @ \$476.00 EACH	44	\$ 952.00	X
1PC	SPARE WHEEL PANEL TOP BOARD	44	\$ 569.00	X
1PC	SPARE WHEEL PANEL TOOL BOX	44	\$ 385.00	X
1PC	REAR EXHAUST PIPE	44	\$ 2,227.00	X
1PC	REAR EXHAUST HEAT SHIELD	44	\$ 126.00	X
1PC	REAR EXHAUST MOUNTING	44	\$ 101.00	X
1PC	FRONT DRIVER SEAT BELT	Activated 725.00	\$ 1,423.00	✓
1PC	FRONT PASSENGER SEAT BELT	Activated 725.00	\$ 1,412.00	✓
2PC	REAR SEAT BELT L+R @ \$1,394.00 EACH	Activated 1378.32	\$ 2,788.00	✓
1PC	SRS CONTROL MODULE	Activated 1485.00	\$ 1,890.00	✓

PARTS SUM: \$ 40,982.40

PARTS LESS 10%: \$ 4,098.24

PARTS TOTAL: \$ 36,884.16

11116.37

10004.73

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY REAR NUMBER PLATE & GARNISH	44	\$ 100.00	X
*	TO SUPPLY REAR END PANEL SEALANT	44	\$ 80.00	X
*	TO SUPPLY FENDER SEALANT	44	\$ 80.00	X
*	TO SUPPLY REAR WINDSCREEN SEALANT	44	\$ 80.00	X
*	TO SUPPLY REAR WINDSCREEN DAMPING SEAL	44	\$ 30.00	X
*	TO SUPPLY BONNET INNER TRIM CLIPS	44	\$ 50.00	X
*	TO SUPPLY TAIL LAMP PANEL SEALANT	44	\$ 80.00	X
*	TO SUPPLY SPARE WHEEL PANEL SEALANT	44	\$ 80.00	X
*	TO SUPPLY REAR END PANEL TOP GARNISH CLIPS	44	\$ 50.00	X
*	TO SUPPLY REAR FENDER INNER TRIM CLIPS	44	\$ 50.00	X
*	TO SUPPLY REAR FENDER INNER SHIELD CLIPS	44	\$ 50.00	X
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS		\$ 300.00	80/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS		\$ 2,000.00	600/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS		\$ 2,000.00	600/-
*	TO TUFF COAT DAMAGED AREAS		\$ 300.00	20/-
*	TO RNR REVERSE CAMERA		\$ 100.00	44
*	TO RNR AFFECTED SEAT BELTS TO FACILITATE REPAIRS		\$ 400.00	250/-
*	TO RNR FRONT CONSOLE TO FACILITATE REPAIRS		\$ 250.00	44
*	TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD		\$ 250.00	44

- * TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD \$ 200.00 60/-
- * TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS \$ 250.00 44
- * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS 1860.00 \$ 200.00 30/-
- * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS \$ 500.00 180/-
- * TO RNR REVERSE SENSOR TO ASSIST WORK LOAD \$ 120.00 40/-

LABOUR & S/N TOTAL: \$ 7,600.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 44,484.16

11864.73

28/05/2021 @ 1030 hr

Not Actual

2/sum 6 days.

R Nju

2KK Auto



Check Part Price

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: