

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21006184/AGS3Q2**Date:** 17/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800042163
Claimant Vehicle No :	SMN4943A	Insured Vehicle No :	SJX9133X
Date of Loss:	22/05/2021	Nature of Claim:	TP
		Claim No:	8636666000SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN4943A	Engine No:	2ARF258671
Make & Model:	TOYOTA LEXUS, 2.5 ES250 AUTO (A)	Chassis No:	JTHBJ1GG602095486
Reg. Date:	24/03/2017 (Man. Year: 2016)	Odometer:	59713 km
Colour:	Black		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,417.83	17,473.53	13,944.30	44.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,540.00	3,850.00	2,690.00	41.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,957.83	21,323.53	16,634.30	43.82
Approved Total (Overridden) (S\$)		17,000.00		
(S\$)	37,957.83	17,000.00	20,957.83	55.21
+ GST 7.00/7.00% (S\$)	2,657.05	1,190.00	1,467.05	55.21
Nett Amount (S\$)	40,614.88	18,190.00	22,424.88	55.21
+ Car Rental (12.0 x S\$150.00/day) (S\$)		1,800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		19,997.45		
Global Sum Settlement (S\$)		19,900.00		

INSPECTION

Date of Assignment:	24/05/2021		
Date Inspected:	24/05/2021	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	10.0 days		

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,285.60 FL	*1,285.60 FL
2	1		*BOOT LID BADGE	Necessary	97.86 FL	*97.86 FL
3	1		*BOOT LID EMBLEM LEXUS	Necessary	94.60 FL	*94.60 FL
4	1		*BOOT LID EMBLEM ES250	Necessary	97.50 FL	*97.50 FL
5	1		*BOOT LID OUTER GARNISH	Cracked	425.90 FL	*425.90 FL
6	1		*SET BOOT LID OUTER GARNISH CLIPS	Necessary	40.00 FL	*10.00 FL
7	2		*BOOT LID NUMBER PLATE LAMPS	Not Necessary	259.40 FL	*- FL
8	1		*BOOT LID OPENER SWITCH	Not Necessary	158.10 FL	*- FL
9	1		*BOOT LID INNER LOCK	Damaged	385.90 FL	*385.90 FL
10	1		*BOOT LID INNER LOCK COVER	Not Necessary	98.60 FL	*- FL
11	2		*BOOT LID LAMPS	N/S Cracked / O/S Cut	1,371.80 FL	*1,050.00 FL
12	2		*BOOT LID LAMPS INNER SEALER	Not Necessary	80.00 FL	*- FL
13	2		*SET BOOT LID LAMPS CLIPS	Necessary	60.00 FL	*20.00 FL
14	2		*BOOT LID STOPPER	Not Necessary	50.00 FL	*- FL
15	1		*BOOT LID INSULATOR	Not Necessary	578.90 FL	*- FL
16	1		*SET BOOT LID INSULATOR CLIPS	Not Necessary	40.00 FL	*- FL
17	1		*BOOT LID POCKET HANDLE	Not Necessary	173.00 FL	*- FL
18	1		*BOOT LID AUTO LOCK ACTUATOR	Not Necessary	481.70 FL	*- FL
19	1		*BOOT LID LOCK CATCH	Not Necessary	66.20 FL	*- FL
20	1		*BOOT LID WEATHERSTRIP	Cut	298.60 FL	*298.60 FL
21	2		*BOOT LID HINGES	Not Necessary	337.80 FL	*- FL
22	2		*BOOT LID HINGES COVERS	Not Necessary	211.80 FL	*- FL
23	1		*REAR BUMPER	Distorted	938.50 FL	*938.50 FL
24	1		*REAR BUMPER SIDE RETAINERS	N/S Damaged	317.80 FL	*158.90 FL
25	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
26	2		*REAR BUMPER SIDE SCREW COVER	Not Necessary	55.40 FL	*- FL
27	1		*REAR BUMPER REINFORCEMENT	Dented	589.60 FL	*589.60 FL
28	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	322.60 FL	*- FL
29	1		*REAR BUMPER SPONGE	Cracked	298.60 FL	*107.00 FL
30	2		*REAR BUMPER TOWING COVER	Not Necessary	72.00 FL	*- FL
31	1		*REAR BUMPER BOTTOM COVER	Torn	245.60 FL	*245.60 FL
32	1		*SET REAR BUMPER BOTTOM COVER CLIPS	Necessary	30.00 FL	*30.00 FL
33	1		*REAR BUMPER REFLECTOR	N/S Cracked	157.00 FL	*78.50 FL
34	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	983.20 FL	*491.60 FL
35	1		*SET REAR REVERSE SENSOR WIRE HARDNESS	Cracked	685.70 FL	*296.00 FL
36	1		*END PANEL	Distorted	785.90 FL	*785.90 FL
37	1		*END PANEL TOP TRIM	Deformed	345.80 FL	*345.80 FL
38	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 FL	*10.00 FL
39	1		*SPARE TYRE PANEL	Repair	938.40 FL	*- FL
40	1		*SPARE TYRE PANEL TOP BOARD	Deformed	359.50 FL	*359.50 FL
41	1		*SPARE TYRE PANEL TOP SIDE SPONGES	N/S Cracked	397.60 FL	*198.80 FL
42	1		*SPARE TYRE PANEL TOP TRAY	Not Necessary	459.60 FL	*- FL
43	1		*SPARE TYRE PANEL TOP INNER INSULATOR	Not Necessary	541.80 FL	*- FL
44	1		*SPARE TYRE WHEEL NUT	Not Necessary	65.20 FL	*- FL
45	1		*REAR KEY ANTENNA SENSOR	Not Necessary	285.90 FL	*- FL
46	1		*REAR CHASSIS FRAME MEMBER LH	Repair	756.20 FL	*- FL
47	2		*TAILLAMPS	N/S Cracked /O/S Cut	1,713.80 FL	*1,454.00 FL
48	1		*TAILLAMPS BRACKETS	N/S Cracked	197.20 FL	*98.60 FL
49	2		*TAILLAMPS INNER SEALER	Not Necessary	72.00 FL	*- FL
50	2		*SET TAILLAMPS CLIPS	Necessary	50.00 FL	*20.00 FL
51	2		*TAILLAMPS SIDE COVER GARNISH	Not Necessary	150.00 FL	*- FL
52	1		*TAILLAMPS PANEL LH	Distorted	358.90 FL	*358.90 FL
53	1		*REAR FENDER LH	Distorted	1,485.90 FL	*1,485.90 FL
54	1		*REAR FENDER TOP SIDE JOINT PANEL LH	Repair	245.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	2		*REAR FENDER TOP SIDE RAILING GARNISH	Not Necessary	172.00 FL	*- FL
56	2		*SET REAR FENDER TOP SIDE RAILING GARNISH CLIPS	Not Necessary	50.00 FL	*- FL
57	1		*REAR FENDER INNER TRIM	N/S Torn	1,167.20 FL	*494.00 FL
58	2		*REAR FENDER INNER TRIM COVER	Not Necessary	166.40 FL	*- FL
59	2		*SET REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FL	*30.00 FL
60	1		*REAR FENDER INNER SHIELD	N/S Torn	357.20 FL	*178.60 FL
61	2		*SET REAR FENDER INNER SHIELD CLIPS	Necessary	50.00 FL	*20.00 FL
62	2		*SET REAR FENDER INNER SHIELD BRACKETS	Not Necessary	171.80 FL	*- FL
63	1		*REAR WHEEL HOUSE PANEL	Repair	645.80 FL	*- FL
64	1		*REAR AIR VENTS	Deformed	179.60 FL	*179.60 FL
65	1		*FUEL LID COVER	Not Necessary	110.00 FL	*- FL
66	1		*FUEL LID COVER LOCK	Not Necessary	65.00 FL	*- FL
67	1		*FUEL TANK	Not Necessary	856.90 FL	*- FL
68	1		*REAR WINDSCREEN MOULDING	Necessary	197.00 FL	*197.00 FL
69	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FL	*60.00 FL
70	1		*REAR WINDSCREEN	Cut	1,598.60 FL	*1,305.00 FL
71	2		*SET ROOF TOP MOULDING CLIPS	Not Necessary	60.00 FL	*- FL
72	2		*REAR EXHAUST SILENCER	Dented	1,712.60 FL	*856.30 FL
73	6		*REAR EXHAUST MOUNTINGS	Not Necessary	351.60 FL	*- FL
74	2		*REAR EXHAUST MOUNTINGS BRACKET	Not Necessary	224.00 FL	*- FL
75	1		*REAR EXHAUST GASKET	Necessary	65.00 FL	*65.00 FL
76	1		*REAR EXHAUST HEAT PLATE	N/S Crumpled	392.60 FL	*196.30 FL
77	1		*REAR EXHAUST GARNISH	N/S Damaged	571.80 FL	*285.90 FL
78	1		*FRONT DRIVER SEATBELT	Activated	1,085.20 FL	*1,085.20 FL
79	1		*FRONT PASSENGER SEATBELT	Activated	1,065.30 FL	*1,065.30 FL
80	2		*FRONT SEATBELT BUCKLES	Not Necessary	691.60 FL	*- FL
81	1		*SRS CONTROL UNIT	Activated	1,658.30 FL	*1,350.00 FL
82	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
83	1		*REAR NUMBER PLATE WITH COVER	Not Necessary	50.00 FS	*- FS
84	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*100.00 FS
85	1		*SET REAR FLOOR PANEL INSULATOR PAD	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	34,864.26	19,397.26
- List Item Discount on L Items 10.00/10.00% (S\$)	3,446.43	1,923.73
Total Parts (S\$)	31,417.83	17,473.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,600.00	1,600.00
2	SPRAY PAINTING	New	2,200.00	1,400.00
3	CHECK WIRING ON REAR TAILAMP	New	120.00	30.00
4	ANTI RUST	New	180.00	100.00
5	REMOVE AND INSTALL REAR WINDSCREEN	New	150.00	120.00
6	REMOVE AND INSTALL CARPET AND SEAT	New	250.00	100.00
7	REMOVE AND INSTALL REVERSE SENSOR	New	120.00	60.00
8	REMOVE AND INSTALL REAR EXHAUST SILENCER	New	150.00	80.00
9	REMOVE AND INSTALL PETROL TANK	New	300.00	80.00
10	REMOVE AND INSTALL BOOTLID MECHANISM	New	150.00	80.00
11	TO JACK AND ALIGNMENT CHASSIS FRAME MEMBER	New	320.00	200.00
Gross Labour Cost (\$\$)			6,540.00	3,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >