

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21006185/ATCE2**Date:** 14/09/2021**REFERENCE**

Insured/Claimant:	LEVENT TAVSANGI	Policy No:	1800107487-02	
Date of Loss:	18/05/2021	Nature of Claim:	OD	Claim No: 5546134449SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ1952M		
Make & Model:	AUDI A6, 1.8 TFSI Ultra (PI) (NAV) (A)	Engine No:	CYG024083
Reg. Date:	17/09/2018 (Man. Year: 2017)	Chassis No:	WAUZZZ4G8JN051479
Colour:	Black	Odometer:	37183 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$130,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,767.00	16,684.32	21,082.68	55.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,944.00	4,072.00	9,872.00	70.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	51,711.00	20,756.32	30,954.68	59.86
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	50,911.00	19,956.32	30,954.68	60.80
+ GST 7.00/7.00% (S\$)	3,563.77	1,396.94	2,166.83	60.80
Nett Amount (S\$)	54,474.77	21,353.26	33,121.51	60.80

INSPECTION

Date of Assignment:	27/05/2021		
Date Inspected:	25/05/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*STICKER FOR AIR CONDITIONER	Not Necessary	20.00 FS	*- FS
2	1		*STICKER FOR SIGN CAUTION	Not Necessary	14.00 FS	*- FS
3	1		*FRONT SIGNAL HORN - LOW TONE	Not Necessary	201.00 FS	*- FS
4	1		*FRONT SIGNAL HORN BRACKET - LH	Not Necessary	47.00 FS	*- FS
5	1		*FRONT SENSOR OUTER	Not Necessary	0.00 FS	*- FS
		(NPA)				
6	4		*FRONT SENSOR SEAL RING	Not Necessary	6.00 FS	*- FS
7	1		*FRONT FENDER - LH	Buckled	1,391.00 FS	*1,112.80 FS
8	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	102.00 FS	*- FS
9	1		*FRONT STONE GUARD FILM - LH	Not Necessary	121.00 FS	*- FS
10	1		*FRONT FENDER BRACE - LH	Bent	96.00 FS	*76.48 FS
11	1		*BONNET	Dented	5,436.00 FS	*4,348.80 FS
12	1		*BONNET ATTACHMENT PARTS	Not Necessary	178.00 FS	*- FS
13	1		*BONNET CATCH HOOK	Not Necessary	140.00 FS	*- FS
14	2		*BONNET LOCK STRIKER PLATE	Not Necessary	100.00 FS	*- FS
15	1		*BONNET LATCH	Not Necessary	18.00 FS	*- FS
16	2		*BONNET LID LOCK WITH MICRO SWITCH - LH / RH	Not Necessary	427.00 FS	*- FS
17	1		*BONNET LOCK COVER	Not Necessary	4.00 FS	*- FS
18	1		*LED HEADLIGHT MOUNTING - LH	Not Necessary	118.00 FS	*- FS
19	1		*LED HEADLIGHT - LH	Cracked	9,540.00 FS	*7,632.00 FS
20	1		*FAN FOR HED HEADLIGHT - LH	Not Necessary	398.00 FS	*- FS
21	1		*LED HEADLIGHT POWER MODULE FOR DAY DRIVING - LH	Not Necessary	553.00 FS	*- FS
22	1		*LED HEADLIGHT CONTROL MODULE - LH	Not Necessary	557.00 FS	*- FS
23	1		*LED HEADLIGHT HOUSING - LH	Not Necessary	34.00 FS	*- FS
24	1		*LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM - LH	Not Necessary	236.00 FS	*- FS
25	1		*HOSE FOR HEADLIGHT WASHER SYSTEM - LH	Not Necessary	488.00 FS	*- FS
26	1		*FRONT LOCK CARRIER	Not Necessary	1,248.00 FS	*- FS
27	1		*FRONT SUPPORT FOR COOLANT REGULATOR	Not Necessary	37.00 FS	*- FS
28	6		*RADIATOR COOLANT	Not Necessary	142.00 FS	*- FS
29	1		*RADIATOR AIR GUIDE - LH	Not Necessary	29.00 FS	*- FS
30	1		*RADIATOR AIR GUIDE UPPER CENTRE - LH	Not Necessary	29.00 FS	*- FS
31	1		*RADAR SENSOR - LH	Not Necessary	5,892.00 FS	*- FS
32	1		*SUNDRIES	Necessary	300.00 FS	*56.24 FS
33	1		*RADAR SENSOR COVER - LH	Not Necessary	13.00 FS	*- FS
34	1		*FRONT NO. PLATE	Not Necessary	60.00 FS	*- FS
35	1		*FRONT BUMPER	Distorted	3,268.00 FS	*2,614.40 FS
36	1		*FRONT BUMPER FIXING PARTS	Not Necessary	543.00 FS	*- FS
37	1		*FRONT BUMPER LOWER GRILLE - CENTER	Not Necessary	128.00 FS	*- FS
38	14		*FRONT BUMPER LOCKING CLIP	Not Necessary	55.00 FS	*- FS
39	1		*FRONT BUMPER ADAPTER	Not Necessary	38.00 FS	*- FS
40	1		*FRONT BUMPER CLOSING ELEMENT	Torn	219.00 FS	*174.80 FS
41	1		*FRONT BUMPER LOWER SPOILER	Not Necessary	249.00 FS	*- FS
42	1		*FRONT BUMPER SHORT SPOILER	Not Necessary	945.00 FS	*- FS
43	1		*FRONT RADIATOR GRILLE	Not Necessary	1,934.00 FS	*- FS
44	2		*FRONT RADIATOR GRILLE SUPPORT SENSOR - LH / RH	Not Necessary	132.00 FS	*- FS
45	1		*FRONT AIR GUIDE GRILLE - LH	Cut	572.00 FS	*457.60 FS
46	1		*FRONT AIR GUIDE GRILLER INNER COVER - LH	Not Necessary	51.00 FS	*- FS
47	1		*FRONT WHEEL SPOILER - LH	Damaged	264.00 FS	*211.20 FS
48	1		*FRONT HEADLIGHT WASHER CAP - LH	Not Necessary	58.00 FS	*- FS
49	1		*FRONT FOAM FILLER PIECE	Not Necessary	237.00 FS	*- FS
50	1		*FRONT REINFORCEMENT BEAM	Not Necessary	872.00 FS	*- FS
51	1		*FRONT REINFORCEMENT BEAM COVER	Not Necessary	123.00 FS	*- FS
52	1		*FRONT FENDER BRACE - LH	Not Necessary	30.00 FS	*- FS
53	1		*FRONT BUMPER GUIDE PIECE - LH	Not Necessary	38.00 FS	*- FS
54	1		*FRONT RADIATOR GRILLE COVER	Not Necessary	36.00 FS	*- FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	37,767.00
						16,684.32
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICALS FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	1,500.00
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER AND BONNET	New	5,200.00	1,650.00
6	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR	New	480.00	0.00
7	TO CARRY OUT PRE / POST DIAGNOSTIC CHECK	New	384.00	192.00
Gross Labour Cost (\$\$)			13,944.00	4,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >