

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21006194/AQCE2

Date: 18/11/2021

REFERENCE

Insured/Claimant:	FU ZHI JUN	Policy No:	2070149506		
Date of Loss:	21/05/2021	Nature of Claim:	OD	Claim No:	9597216436SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV7627B		
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Engine No:	DEM025290
Reg. Date:	20/10/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF48MA001132
Colour:	Black	Odometer:	14044 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,640.00	5,438.88	21,201.12	79.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,984.00	5,082.00	13,902.00	73.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,624.00	10,520.88	35,103.12	76.94
- Excess (S\$)	3,550.00	3,550.00	0.00	0.00
(S\$)	42,074.00	6,970.88	35,103.12	83.43
+ GST 7.00/7.00% (S\$)	2,945.18	487.96	2,457.22	83.43
Nett Amount (S\$)	45,019.18	7,458.84	37,560.34	83.43

INSPECTION

Date of Assignment:	28/05/2021		
Date Inspected:	25/05/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,233.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	358.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	44.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	135.00 FS	*- FS
6	1		*FRONT BUMPER TRIM - LH	Not Necessary	48.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	36.00 FS	*- FS
8	1		*FRONT FENDER - LH	Dented	1,092.00 FS	*873.60 FS
9	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	202.00 FS	*- FS
10	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	72.00 FS	*- FS
11	1		*FRONT FENDER LONG BRACKET - LH	Not Necessary	35.00 FS	*- FS
12	1		*FRONT FENDER DEFORMATION BRACKET - LH	Not Necessary	49.00 FS	*- FS
13	1		*FRONT FENDER SHORT BRACKET	Not Necessary	32.00 FS	*- FS
14	1		*FRONT FENDER BRACE - LH	Not Necessary	118.00 FS	*- FS
15	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	33.00 FS	*- FS
16	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	236.00 FS	*- FS
17	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	139.00 FS	*- FS
18	1		*FRONT WHEEL SPOILER - LH	Not Necessary	73.00 FS	*- FS
19	1		*FRONT WHEEL SPOILER TRIM - LH	Not Necessary	31.00 FS	*- FS
20	1		*HEADLIGHT COVER	Not Necessary	44.00 FS	*- FS
21	1		*HEADLIGHT = LH	Not Necessary	7,685.00 FS	*- FS
22	1		*A/B PILLAR SECTIONAL PART - LH	Repair	2,675.00 FS	*- FS
23	1		*FRONT DOOR - LH	Dented	3,192.00 FS	*2,553.60 FS
24	1		*FRONT OUTER DOOR SEAL - LH	Necessary	205.00 FS	*164.00 FS
25	1		*FRONT DOOR BONDING AGENT	Not Necessary	48.00 FS	*- FS
26	1		*FRONT DOOR CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
27	1		*FRONT DOOR APPLICATOR	Not Necessary	8.00 FS	*- FS
28	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	1,050.00 FS	*- FS
29	1		*FRONT DOOR CATCH LH	Not Necessary	105.00 FS	*- FS
30	1		*FRONT DOOR UPPER HINGE - LH	Not Necessary	44.00 FS	*- FS
31	1		*FRONT DOOR UPPER HINGE HALVES - LH	Not Necessary	46.00 FS	*- FS
32	1		*FRONT DOOR LOWER HINGE - LH	Not Necessary	47.00 FS	*- FS
33	1		*FRONT DOOR LOWER HINGE HALVES - LH	Not Necessary	45.00 FS	*- FS
34	1		*FRONT DOOR INNER SEAL	Not Necessary	205.00 FS	*- FS
35	1		*FRONT WING MIRROR MOUNTING - LH	Cut	1,089.00 FS	*871.20 FS
36	1		*FRONT WING MIRROR CAP - LH	Not Necessary	289.00 FS	*- FS
37	1		*FRONT WING MIRROR GLASS - LH	Not Necessary	1,229.00 FS	*- FS
38	1		*FRONT DOOR WINDOW REGULATOR - LH	Not Necessary	282.00 FS	*- FS
39	1		*FRONT DOOR WINDOW SLOT SEAL TRIM - LH	Not Necessary	307.00 FS	*- FS
40	1		*FRONT DOOR WINDOW GUIDE TRIM STRIP	Not Necessary	257.00 FS	*- FS
41	1		*FRONT A-PILLAR TRIM	Not Necessary	228.00 FS	*- FS
42	1		*FRONT SILL TRIM STRIP	Not Necessary	120.00 FS	*- FS
43	1		*FRONT ALUMINIUM RIM LH	Cut	1,155.00 FS	*924.00 FS
44	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
45	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
46	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
47	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
48	1		*SUNDRIES	Necessary	400.00 FS	*52.48 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **26,640.00** **5,438.88**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	350.00	280.00
3	TO REMOVE AND REINSTALL DASHBOARD ASSY AND CENTRE CONSOLE TO FACILITATE THE RENEWAL OF LHS A-PILLAR AND LHS SILL PANEL	New	3,200.00	0.00
4	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, ABCD PILLAR TRIMS. SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	0.00
5	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	0.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS HEADLIGHT. TO CUT AND WELD LHS A-PILLAR AND LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	1,500.00
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR, HINGES, LHS WING MIRROR COVER, DOOR ENTRANCE. LHS A-PILLAR AND LHS SILL PANEL	New	5,300.00	1,800.00
8	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	280.00
9	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
10	TO RESPRAY LHS UPPER A-PILLAR (Supplementary)	New	1,000.00	550.00
Gross Labour Cost (\$\$)			18,984.00	5,082.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >