

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006195/R1TCN2**Date:** 14/01/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00041762003		
Claimant Vehicle No :	SMW4154M	Insured Vehicle No :	GBF1031Z		
Date of Loss:	20/05/2021	Nature of Claim:	TP	Claim No:	SNM21D202936/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW4154M		
Make & Model:	MAZDA 6, 2.0 (A)	Engine No:	PE20981396
Reg. Date:	19/02/2018 (Man. Year: 2017)	Chassis No:	JM6GL1071J0129694
Colour:	Red	Odometer:	40406 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,344.96	2,917.92	427.04	12.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,040.00	790.00	250.00	24.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,384.96	3,707.92	677.04	15.44
Approved Total (Overridden) (\$\$)		3,350.00		
(\$\$)	4,384.96	3,350.00	1,034.96	23.60
+ GST 7.00/7.00% (\$\$)	306.95	234.50	72.45	23.60
Nett Amount (\$\$)	4,691.91	3,584.50	1,107.41	23.60

INSPECTION

Date of Assignment:	28/05/2021		
Date Inspected:	02/06/2021	Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2022)
Parts:	143	MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW4154M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	1,015.20 FL	*1,015.20 FL
2	1		*REAR BOOT LOGO	Necessary	49.20 FL	*49.20 FL
3	1		*REAR BOOT EMBLEM MAZDA	Necessary	58.60 FL	*58.60 FL
4	1		*REAR BOOT EMBLEM 6	Necessary	28.60 FL	*28.60 FL
5	1		*REAR BOOT EMBLEM SKYACTIVE	Necessary	74.70 FL	*74.70 FL
6	1		*REAR BOOT LAMP RH	Cracked	344.10 FL	*344.10 FL
7	1		*REAR BOOT LOCK	Serviceable	160.00 FL	*- FL
8	1		*REAR LAMP RH	Cracked	762.80 FL	*762.80 FL
9	1		*REAR BUMPER	Deformed	1,266.20 FL	*1,266.20 FL
10	1		*REAR BUMPER REFLECTOR LH	Not Necessary	53.10 FL	*- FL
11	10		*REAR BUMPER CLIPS	Necessary	48.00 FL	*48.00 FL
12	1		*REAR BUMPER SENSOR RH	Not Necessary	278.60 FL	*- FL
13	1		*REAR BUMPER SENSOR COVER RH	Not Necessary	42.10 FL	*- FL
14	1		*REAR END PANEL (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*REAR FENDER RH (NPA)	Not Necessary	0.00 FL	*- FL
16	1		*REAR REINFORCEMENT (NPA)	Not Necessary	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,181.20	3,647.40
- List Item Discount on L Items 20.00/20.00% (S\$)	836.24	729.48
Total Parts (S\$)	3,344.96	2,917.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT AND WELD,TO REPAIR REAR END PANEL,REAR FENDER RH,TO REMOVE & REFIX DAMAGED PARTS,STRAIGHTEN AND REALIGN AFFECTED AREAS	New	350.00	350.00
2	TO SPRAY AFFECTED AREAS	New	600.00	400.00
3	TO REMOVE & REFIX REAR LUGGAGE COMPARTMENT SIDE COVER,SIDE GARNISH AND OTHER ATTACHMENT PARTS	New	50.00	0.00
4	TO RUST PROOF AFFECTED AREAS	New	40.00	40.00
Gross Labour Cost (\$)			1,040.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >