

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006198/UGS3Q2
Date: 27/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800024901
Claimant Vehicle No :	SMY3833H	Insured Vehicle No :	SLX365D
Date of Loss:	25/05/2021	Nature of Claim:	TP
		Claim No:	3499689820SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY3833H		
Make & Model:	TOYOTA WISH, 2.0 (A)	Engine No:	3ZRA438354
Reg. Date:	01/02/2010 (Man. Year: 2009)	Chassis No:	JTDGJ20W805001816
Colour:	Grey	Odometer:	147236 km
Engine Capacity:	1987 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Rotalla 7 mm	Rear Left Side:	Rotalla 7 mm
Front Right Side:	Rotalla 7 mm	Rear Right Side:	Rotalla 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,310.50	3,912.25	4,398.25	52.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,820.00	2,340.00	1,480.00	38.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,130.50	6,252.25	5,878.25	48.46
Approved Total (Overridden) (S\$)		5,000.00		

Nett Amount (S\$)	12,130.50	5,000.00	7,130.50	58.78
		+ Car Rental (6.0 x S\$120.00/day) (S\$)	720.00	
		+ Doc/Search Fee (S\$)	7.45	
		Nett Liability (S\$)	5,727.45	

INSPECTION

Date of Assignment: 28/05/2021

Date Inspected: 28/05/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Asia Motorsports Solution Pte Ltd (HQ)
 37A Everitt
 Singapore 428586

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented	1,272.00 FL	*1,272.00 FL
2	1		*TAIL GATE CENTRE BADGE	Necessary	85.50 FL	*68.10 FL
3	1		*TAIL GATE CENTRE CHROME GARNISH	Not Necessary	328.00 FL	*- FL
4	1		*TAIL GATE INNER LOCK	Shorted / Jammed	238.00 FL	*238.00 FL
5	1		*TAIL GATE INNER TRIM BOARD	Deformed / Cracked	288.00 FL	*288.00 FL
6	2		*TAIL GATE HINGES (NPA)	Not Necessary	0.00 FL	*- FL
7	2		*TAIL GATE RUBBER STOPPER	Not Necessary	64.00 FL	*- FL
8	2		*TAIL GATE DAMPERS	Not Necessary	576.00 FL	*- FL
9	2		*TAIL GATE REFLECTOR RHS & LHS	Not Necessary	997.00 FL	*- FL
10	2		*REAR WINDSCREEN INNER MOULDING	Necessary	150.00 FL	*150.00 FL
11	1		*TAILGATE WIPER MOTOR (NPA)	Not Necessary	0.00 FL	*- FL
12	1		*TAILGATE WIPER BLADE (NPA)	Not Necessary	0.00 FL	*- FL
13	2		*RHS & LHS TAILLAMPS	Cracked	1,451.00 FL	*970.20 FL
14	1		*REAR TAILGATE TOP SPOILER (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*REAR BUMPER	Distorted	1,122.00 FL	*581.10 FL
16	2		*REAR BUMPER REFLECTORS	Not Necessary	150.00 FL	*- FL
17	2		*REAR BUMPER SIDE RETAINERS	Serviceable	180.00 FL	*- FL
18	2		*REAR BUMPER EXTENSION BRACKET	Serviceable	356.00 FL	*- FL
19	1		*RHS REAR FENDER (NPA)	Repair	0.00 FL	*- FL
20	1		*LHS REAR FENDER	Repair	782.00 FL	*- FL
21	1		*LHS REAR FENDER INNER SIDE TRIM (NPA)	Not Necessary	0.00 FL	*- FL
22	1		*LHS REAR FENDER GLASS (NPA)	Not Necessary	0.00 FL	*- FL
23	1		*REAR BOOT EDGE WEATHERSTRIP	Twisted	287.50 FL	*287.50 FL
24	1		*REAR END PANEL LOCK CATCH	Not Necessary	66.00 FL	*- FL
25	1		*REAR END PANEL TOP GARNISH	Deformed / Twisted	289.00 FL	*289.00 FL
26	1		*REAR END PANEL	Dented / Bent	782.00 FL	*619.10 FL
27	1		*REAR FLOOR BOARD TOOL TRAY	Not Necessary	325.00 FL	*- FL
28	1		*REAR FLOOR BOARD TOP COVER	Not Necessary	245.00 FL	*- FL
29	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
30	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
31	1		*REVERSE CAMERA (NPA)	Not Necessary	0.00 FS	*- FS
32	1		*SET LHS REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
33	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
34	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
35	1		*LHS REAR FENDER GLASS SEALANT	Not Necessary	120.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	75.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					10,819.00	5,103.00
- List Item Discount on L Items 25.00/25.00% (S\$)					2,508.50	1,190.75
Total Parts (S\$)					8,310.50	3,912.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,400.00	880.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS I.E (RHS REAR FENDER)	New	1,250.00	1,100.00
3	TO REMOVE ,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION	New	200.00	30.00
4	TO REMOVE/REFIT INNER TRIMS ,FITTINGS ,GARNISH ,ETC AT REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR	New	250.00	100.00
5	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN	New	140.00	120.00
6	TO REMOVE AND REFIX REAR LHS REAR FENDER GLASS	New	100.00	0.00
7	TO REMOVE AND REFIX REAR TAILGATE TOP SPOILER	New	120.00	0.00
8	TO REMOVE AND REFIX REVERSE CAMERA AND CHECK FOR PROPER FUNCTION	New	120.00	0.00
9	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTION	New	120.00	50.00
10	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	120.00	60.00
Gross Labour Cost (\$\$)			3,820.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >