

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMY3833H
Asia motorsports

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$ 55k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

047D

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMY3833H

Yr Regn:

01/02/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA 7

Make:

Toyota wish

c.c

1987

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

147236

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDGJ 20W805001816

Gen. Cond: Good / Fair / Poor / Burnt

Steering: norder / Jammed / Leaked / Burnt or

Brake: norder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Rotalla

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

25/5/21

D.O.I.

28/5/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Cue 4461 31-01-2030 HTA 34222

2/6/21 1/5 \$5000 cont. med with AH long

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

4/4/21 Cecilia

*not Authorized
28/5/21*

*L/s \$5000
Page No. 1 5 days.*

Vehicle No. **SMY 3833H** **TOYOTA WISH**

When photo After repair

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Tail Gate	<i>DD</i>	1272.00	✓
1	Tail Gate Centre badge	<i>neu</i>	85.50	✓
1	Tail Gate Centre Chrome Garnish	<i>17</i>	328.00	X
1	Tail Gate inner Lock	<i>shutd/ym</i>	238.00	✓
1	Tail Gate Inner Trim Board	<i>Def/cno</i>	288.00	✓
2	Tail Gate hinges	REUSE <i>17</i>	0.00	X
2	Tail Gate rubber stopper @32.00	<i>17</i>	64.00	X
2	Tail Gate Dampers @ \$288.00	<i>17</i>	576.00	X
2	Tail Gate Reflectors RHS & LHS @498.50	<i>17</i>	997.00	X
2	Rear Windscreen Inner Moulding @ \$75.00	<i>neu</i>	150.00	✓
1	Tailgate wiper motor	REFIX <i>17</i>	0.00	X
1	Tailgate wiper blade	REFIX <i>17</i>	0.00	X
2	RHS & LHS Taillamps @ \$725.50 <i>485.10 X</i>	<i>CNR</i>	970.20 <i>1451.00</i>	✓
1	Rear tailgate top spoiler	REFIX <i>17</i>	0.00	X
1	Rear Bumper	<i>D.S</i>	581.10 <i>1122.00</i>	✓
2	Rear Bumper reflectors @ \$75.00	<i>CNR</i>	150.00	X
2	Rear Bumper Side Retainers @ \$90.00	<i>SVC</i>	180.00	X
2	Rear Bumper extension bracket @178.00	<i>8u</i>	356.00	X
1	RHS Rear Fender	REPAIR/PAINIT <i>17</i>	0.00	X
1	LHS Rear Fender	<i>17</i>	782.00	X
1	LHS Rear Fender inner side trim	Refix <i>17</i>	0.00	X
1	LHS Rear Fender glass	Refix <i>17</i>	0.00	X
1	Rear Boot Edge Weatherstrip	<i>twi</i>	287.50	✓
1	Rear End Panel Lock Catch	<i>17</i>	66.00	X
1	Rear End Panel Top Garnish	<i>Def/ym</i>	289.00	✓
1	Rear End Panel	<i>DD/Def</i>	619.10 <i>782.00</i>	✓
1	Rear Floor board tool tray	<i>17</i>	325.00	X
1	Rear Floor board top cover	<i>17</i>	245.00	X
			10034.00	
less 25%			2508.50	25%
			7525.50	
<u>SPECIAL NETT ITEMS</u>				
1	Rear Windscreen Sealant	<i>neu</i>	100.00	40
1	Reverse Sensor	<i>shutd</i>	280.00	200
1	Reverse camera	REFIX <i>17</i>	0.00	X
1 set	LHS Rear fender inner shield clips	<i>17</i>	50.00	X
1 set	Rear Bumper Clips	<i>neu</i>	60.00	50
1	Rear End Panel Sealant	<i>neu</i>	100.00	50
1	LHS Rear fender glass sealant	<i>17</i>	120.00	X
1	Rear licence plate w/holder	<i>17</i>	75.00	X
TOTAL PARTS			8310.50	

Vehicle No. SMY 3833H TOYOTA WISH

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1400.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas i.e (RHS Rear fender)	1250.00	1100
3	To remove, refix wiring system at accident damaged areas and check for proper function	200.00	30
4	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	250.00	100
5	To remove and refix rear tailgate windscreen	140.00	120
6	To remove and refix rear LHS rear fender glass	100.00	unx
7	To remove and refix rear tailgate top spoiler	120.00	unx
8	To remove and refix reverse camera and check for proper function	120.00	unx
9	To remove and replace reverse sensors and check for proper function	120.00	50
10	To perform anti-rust treatment on affected areas	120.00	60
	Labour Total :	3820.00	
	TOTAL (PARTS & LABOUR):	12130.50	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4703
252
9-3572-25
S.N- 340
L- 2340
628225