

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21006199/AGA3Q2**Date:** 16/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900262104
Claimant Vehicle No :	SLQ202C	Insured Vehicle No :	SMR2479R
Date of Loss:	27/05/2021	Nature of Claim:	TP
		Claim No:	4458111871SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ202C	Engine No:	CZDC23676
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF36M1062583
Reg. Date:	24/03/2021 (Man. Year: 2020)	Odometer:	2911 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,454.00	1,357.20	11,096.80	89.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,272.00	1,722.00	1,550.00	47.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,726.00	3,079.20	12,646.80	80.42
+ GST 7.00/7.00% (S\$)	1,100.82	215.54	885.28	80.42
Nett Amount (S\$)	16,826.82	3,294.74	13,532.08	80.42
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,476.74		

INSPECTION

Date of Assignment:	28/05/2021		
Date Inspected:	28/05/2021	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,008.00 FS	*806.40 FS
2	1		*FRONT BUMPER CONNECTING PIECE	Not Necessary	145.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT LH	Not Necessary	59.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE -CENTER	Not Necessary	217.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE -LH	Not Necessary	110.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Not Necessary	383.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE LH	Cut	153.00 FS	*122.00 FS
9	1		*RADIATOR GRILLE	Not Necessary	1,433.00 FS	*- FS
10	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	244.00 FS	*- FS
11	1		*FOAM FILLER PIECE	Not Necessary	102.00 FS	*- FS
12	1		*FRONT REINFORCEMENT BEAM	Not Necessary	916.00 FS	*- FS
13	1		*FRONT BUMPER TOP COVER	Not Necessary	123.00 FS	*- FS
14	1		*FRONT BUMPER GUIDE SECTION LH	Not Necessary	39.00 FS	*- FS
15	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
16	1		*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
17	1		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
18	1		*FRONT WHEEL HOUSING LINER LH	Not Necessary	240.00 FS	*- FS
19	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	101.00 FS	*- FS
20	1		*HEADLIGHT MOUNTING LH	Not Necessary	118.00 FS	*- FS
21	1		*LED HEADLIGHT LH	Not Necessary	5,589.00 FS	*- FS
22	1		*HEADLIGHT LIFT CYLINDER LH	Not Necessary	210.00 FS	*- FS
23	1		*HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	80.00 FS	*- FS
24	2		*FRONT WHEEL ARCH COVER LH/RH	Necessary	536.00 FS	*428.80 FS
25	1		*RADIATOR AIR GUIDE LH	Not Necessary	38.00 FS	*- FS
26	1		*RADIATOR AIR GUIDE UPPER	Not Necessary	42.00 FS	*- FS
27	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 12,454.00 1,357.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
4	TO RESPRAY FRONT BUMPER	New	1,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			3,272.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >