

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21006208/KVF3E2

Date: 17/06/2021

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. Policy No: 0999993623

Date of Loss: 20/05/2021

Nature of Claim: OD

Claim No: 7205226894SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK2008R**
Make & Model: MERCEDES-BENZ GLC300, 2.0 4MATIC (R18 LED) (A) Engine No: 26492080086791
Reg. Date: 15/03/2021 (Man. Year: 2020) Chassis No: W1N2539842F855100
Colour: Metallic Blue Odometer: 4725 km
Engine Capacity: 1991 cc
Market Value/New Car Price: S\$240,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18
Front Left Side: Pirelli 9 mm Rear Left Side: Pirelli 9 mm
Front Right Side: Pirelli 9 mm Rear Right Side: Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,883.10	2,575.10	308.00	10.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	200.00	600.00	75.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,683.10	2,775.10	908.00	24.65
- Excess (S\$)	1,700.00	1,700.00	0.00	0.00
(S\$)	1,983.10	1,075.10	908.00	45.79
+ GST 7.00/7.00% (S\$)	138.82	75.26	63.56	45.79
Nett Amount (S\$)	2,121.92	1,150.36	971.56	45.79

INSPECTION

Date of Assignment: 28/05/2021

Date Inspected: 31/05/2021 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*STEPBOARD GARNISH - RH (WCP)	Torn	1,280.00 F	*1,280.00 F
2	1		*STEPBOARD INNER CARRIER - RH (WCP)	Cracked	360.00 F	*360.00 F
3	1		*STEPBOARD INSERT - RH (WCP)	Serviceable	280.00 F	*- F
4	1		*STEPBOARD TOP CHROME - RH (WCP)	Missing	455.00 F	*455.00 F
5	1		*STEPBOARD NUBBED INSERT - RH (FRONT) (WCP)	Missing	30.00 F	*30.00 F
6	1		*STEPBOARD NUBBED INSERT - RH (CENTRE) (WCP)	Missing	40.00 F	*40.00 F
7	1		*STEPBOARD NUBBED INSERT - RH (REAR) (WCP)	Missing	32.00 F	*32.00 F
8	16		*STEPBOARD CLIPS - RH (WCP)	Necessary	144.00 F	*144.00 F

F=Franchise part.

Sub Total (\$\$)	2,621.00	2,341.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	262.10	234.10
Total Parts (\$\$)	2,883.10	2,575.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE & REFIT ABOVE PARTS	New	800.00	200.00
Gross Labour Cost (\$\$)			800.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >