

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21002031/R1TF3E2-1

Date: 08/06/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : MCM4544 **Insured Vehicle No :** SLR8362R
Date of Loss: 22/01/2021 Nature of Claim: TP Claim No: MFL2021D0000452

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **MCM4544**
Make & Model: YAMAHA LC135, 134cc Engine No: G399E215953
Reg. Date: 27/03/2014 (Man. Year: 2014) Chassis No: PMYU00410E0215953
Colour: Blue Odometer: 397865 km
Engine Capacity: 135 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90-17 Rear Tyre Size: 70/90-17
Front Left Side: Maxxis 5 mm Rear Left Side: Maxxis 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	128.70	112.50	16.20	12.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	250.00	100.00	150.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	378.70	212.50	166.20	43.89
Approved Total (Overridden) (S\$)		150.00		
Nett Amount (S\$)	378.70	150.00	228.70	60.39

INSPECTION

Date of Assignment: 28/05/2021
Date Inspected: 11/02/2021 Inspected At: San Tee Auto Pte Ltd (HQ)
BLK 1019 #01-388 YISHUN INDUSTRIAL PARK A
Singapore 768761
Estimated Period of Repair: 1.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 08 Jun 2021)	
Parts:	N/A	YAMAHA LC135 134cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for MCM4544)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET MIRROR	Broken	58.00 FL	*58.00 FL
2	1		*GEAR PEDAL	Bent	39.00 FL	*39.00 FL
3	1		*BRAKE LEVER	Serviceable	18.00 FL	*- FL
4	1		*SET FOOTREST STEP RUBBER PAD	N/S Missing / O/S Torn	28.00 FL	*28.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					143.00	125.00
- List Item Discount on L Items 10.00/10.00% (S\$)					14.30	12.50
Total Parts (S\$)					128.70	112.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE (2 TRIPS)	New	70.00	40.00
2	LABOUR CHARGES TO REMOVE AND DAMAGED PARTS AND TO RE-ALIGN FORKS	New	150.00	60.00
3	TO CHECK WIRING AND LIGHTING FOR CONDITION	New	30.00	0.00
Gross Labour Cost (\$)			250.00	100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >