

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21006216/Evce2	
	8 SHENTON WAY TOWERSINGAPOR	-	Date	14/06/2021	
	ATTN: TAN JUN H	ONG	Code	e: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 3745P	Veh. Inspected	FBR 589A	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S1M03AMJ	Excess (\$)	0.00	
	Assign From	TAN JUN HONG	Assign Date	27/05/2021	
2.	. Vehicle Particulars & Condition				
	Make & Model	YAMAHA CZD300A	c.c	292	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	MH3SH0848KK007084	Colour	SILVER	
	Odometer	14756 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	120/70-15	DUNLOP	4 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	140/70-14	DUNLOP	4 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
5.	General Information				
	Accident Date	12/05/2021	Inspect Date / Time	04/06/2021 (12:00 PM)	
	Survey held at	BLK 171 BUKIT BATOK WEST	AVE 8 SINGAPORE 650	171	
	Repairer	M 1 MOTORING			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b.	5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM21006216/Evce2

Inspected By

CHEN TSUE YEE

HEN ISUE TEE

Automotive Assessor

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser