

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN		Ref:	CS3/LPC21006224/Etf3e2	
	300 BEACH ROAD SINGAPORE 1995		Date:	11/06/2021	
				Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	XB 8263K	Veh. Inspected		GBE 7772J
	Policy No.	olicy No. Coverage (\$)			0.00
	Claim No.	20/21/21/VC00/024599	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		31/05/2021
2.	Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA	c.c		2982
	Engine No.	HIDDEN	Year of Reg.		2016
	Chassis No.	JTFAT35Y80K206111	Colour		SILVER
	Odometer	147088 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	106/104R	BRIDGESTONE		5 mm
	L/H Front Tyre	106/104R	BRIDGESTONE		5 mm
	R/H Rear Tyre	106/104R	BRIDGESTONE		5 mm
	L/H Rear Tyre	106/104R	BRIDGESTONE		5 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRONT PORTION.			
5.	General Information				
	Accident Date	21/05/2021	Inspect Date / 1	Гіте	31/05/2021 ( 10:00 AM )
	Survey held at	GOLD AUTOWORKS PTE LTD			
		48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC21006224/Etf3e2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

**Automotive Assessor** 

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser