

ASS. BY:

REF:

CS/CTI 21006225/D+J3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TPWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. of Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMX 8104 B Yr Regn: Jan / 2021Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz GLA180 c.c 1595Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 7828 T/Radio: Insured / Std / NI / NAEng/No: 27091031901711C/No: WDC1569422J651885Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/80 R18R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. S mmR/Bal. S mmL/Bal. S mmL/Bal. S mmD.O.A. 28/05/2021D.O.I. 31/05/2021Survey held at CS Ong

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time

Action / Instruction

Chung Taping XE 5364 G29/07/21 from 1/5 2600 - with 4 days of repair

red: 25450.25;90%

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

Report Format: _____

Lum Sum / I.E.R. (%)

C. S. ONG AUTO PTE LTD

10, ANG MO KIO IND PARK 2A, #02-16 AMK AUTOPOINT, SINGAPORE 568047

TEL: 6484 1933 | FAX: 6484 1922

E-Mail: csongauto@yahoo.com.sg

To: CHINA TAIPING INSURANCE SINGAPORE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING XE5364G [YOUR INSURED] & SMX8104B [OUR CLIENT]
ON 28/05/2021.

ESTIMATED REPAIR COSTS FOR SMX8104B

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	TAILGATE HW	\$ 2,789.00	X
1PC	TAILGATE LOGO HW	\$ 101.00	X
1PC	TAILGATE 'GLA180' EMBLEM HW	\$ 98.00	X
1PC	TAILGATE LAMP RH HW	\$ 798.00	X
1PC	TAILGATE WEATHER STRIP HW	\$ 490.00	X
1PC	TAILGATE WINDSCREEN MOULDING HW	\$ 390.00	X
1PC	TAILGATE SIDE GARNISH RH CW	328.10 \$ 401.50	✓
1PC	TAIL LAMP RH HW	\$ 1,482.00	X
1PC	TAIL LAMP LOWER BRACKET RH HW	\$ 201.00	X
1PC	REAR BUMPER HW	\$ 1,980.00	X
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$195.00 EACH HW	\$ 390.00	X
1PC	REAR BUMPER TOP SCRUFF PLATE HW	\$ 1,014.00	X
1PC	REAR BUMPER LOWER LID HW	\$ 1,192.00	X
1PC	REAR BUMPER EXHAUST CHROME RH HW	\$ 479.00	X
1PC	REAR BUMPER LOWER LID TOW HOOK COVER HW	\$ 98.00	X
1PC	REAR FENDER RH CW	2255.00 \$ 2,890.00	✓
1PC	REAR FENDER INNER PANEL RH HW	\$ 1,992.00	X
1PC	REAR FENDER INNER TRIM RH HW	\$ 1,097.00	X
1PC	REAR FENDER ARC GARNISH RH HW	\$ 321.00	X
1PC	REAR FENDER INNER SHIELD RH HW	\$ 201.00	X
1PC	REAR DOOR RH HW	\$ 2,980.00	X
1PC	REAR DOOR WEATHER STRIP RH SW	\$ 468.00	X
1PC	REAR DOOR LOWER MOULDING RH SW	\$ 269.00	X
1PC	REAR DOOR TOP MOULDING RH SW	\$ 301.00	X

PARTS SUM: \$ 22,422.50

PARTS LESS 10%: \$ 2,242.25

PARTS TOTAL: \$ 20,180.25

2593.10

2324.79

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY REAR WINDSCREEN SEALANT H4	\$	80.00	X
*	TO SUPPLY REAR WINDSCREEN DAMPING SEAL H4	\$	30.00	X
*	TO SUPPLY REAR WINDSCREEN INNER SEAL H4	\$	80.00	X
*	TO SUPPLY REAR FENDER SEALANT H4	\$	80.00	40/-
*	TO SUPPLY REAR FENDER INNER TRIM CLIPS H4	\$	80.00	X
*	TO SUPPLY REAR FENDER INNER SHIELD CLIPS H4	\$	50.00	X
*	TO SUPPLY REAR FENDER ARC GARNISH CLIPS H4	\$	50.00	X
*	TO SUPPLY TAILGATE INNER TRIM CLIPS H4	\$	50.00	X
*	TO SUPPLY REAR BUMPER CLIPS H4	\$	50.00	X
*	TO SUPPLY REAR BUMPER LOWER LID CLIPS H4	\$	50.00	X
*	TO SUPPLY 1PC TYRE H4	\$	500.00	X
*	TO SUPPLY REAR FENDER EMBLEM H4	\$	200.00	80/-
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$	300.00	80/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$	2,000.00	500/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$	2,000.00	400/-
*	TO TUFF COAT DAMAGED AREAS	\$	300.00	40/-
*	TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS	\$	200.00	H4
*	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	\$	400.00	H4
*	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	\$	150.00	H4
*	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	\$	400.00	H4
*	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	\$	120.00	H4
*	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	\$	200.00	H4
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$	200.00	H4
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$	300.00	H4

LABOUR & S/N TOTAL: \$ 7,870.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 28,050.25

31/05/2021 @ 1030am

H4 Antenna

2/sum

4 days.

J nyan

2kk Antenna

LK Auto Consultants hereby notify the Repayer of the following:

- To receive before/after spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- To legal modification is allowed
- Supplementary items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repayer:
Signature:
Date:

3464.79

4/s 2600/-

Check part prices.