

SM# 7320A.

Honda Stream.

TP China.

Veron.

JHMRN684085205861.

|                                  |            |                            |
|----------------------------------|------------|----------------------------|
| Rear Number Plate                | 2 Not on   | 30(SN) X                   |
| Rear Number Plate Holder         |            | 30(SN) X                   |
| Rear Bumper Distorted            |            | 683.40 ✓                   |
| Rear Bumper Clips                | Rear       | 30(SN) ✓                   |
| Rear Bumper Side Holder x 02     | Bent       | 28.2 X 2 = 56.40 ✓         |
| Rear Bumper Lower Brackett. x 02 | Deformed   | 25.5 X 2 = 51 ✓            |
| Rear Bumper Lower Cover          | Deformed   | 28.70 ✓                    |
| Release Sensor (4 pieces).       | Deformed   | <del>350(SN)</del> 280(SN) |
| Rear End Panel                   | Dented     | 425.90 ✓                   |
| Rear End Panel Top Garnish       | Crushed    | 165.40 ✓                   |
| Rear End Panel Top Garnish Clips | on         | 20(SN) ✓                   |
| Rear End Panel Sealant           | on         | 60(SN) ✓                   |
| Rear End Panel Inner Member      | Dented     | 279.60 ✓                   |
| Tail Lamp x 02                   | Lt Crushed | 368.2 X 2 = 736.40 ✓       |
|                                  |            | 368.20                     |

2946.80

# SME 7320A.

|                                     |            |                    |   |
|-------------------------------------|------------|--------------------|---|
| Tailgate                            | Distorted  | 903.               | ✓ |
| Tailgate Lock                       | Dgd        | 183.70             | ✓ |
| Tailgate Weatherstripe.             | lt         | 116.90             | ✓ |
| Tailgate Inner Trim Board           | auth       | 288.60             | ✓ |
| Tailgate Inner Trim Board clips     | in         | 30(SN)             | ✓ |
| Tailgate Outer Garnish              | MP<br>in   | 184.50             | X |
| Tailgate Glass Moulding?            |            | 108                | ✓ |
| Tailgate Glass Sealant.             | Mec        | 60(SN)             | ✓ |
| Honda Logo.                         | XHE mec    | 35.40              | X |
| Stream Emblem.                      | Mec        | 45.90              | ✓ |
|                                     | LT Guld    | 316.20             |   |
| Rear Fender Inner Trim Board x 2    |            | 316.2 x 2 = 632.40 |   |
| Rear Fender Inner Trim Board clips. | in         | 60(SN) 30(SN)      |   |
| Floor Panel Top Board               | XLP<br>mec | 277.30             | X |
| Rear Exhaust Pipe.                  | 2          | 567.               | X |
| Rear Exhaust Mountry.               | MP<br>in   | 30.40              | X |

3523.10

SME 7320A.

Panel Beating

Spray Painting.

Wiring.

To spray tuff coat.

To remove reverse sensor

To remove upholstery.

To transfer tailgate fittings.

To remove tailgate glass

To remove exhaust pipe.

To remove rear camera

10,099.90

~~1400~~ 900

~~1200~~ 800

~~50~~ 30

~~150~~ 60

~~100~~ 50

~~150~~ 60

~~150~~ 80

~~180~~ 120

~~150~~ X

~~100~~ 50 3630

List: 4020.90

Labors: 2150

Len 20%: 3216.72

total: 5876.72

S N: 510

H/S: 47K

07 Dm/s.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: