



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FG 2298L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR MUDGUARD	DEFORMED	165.00	165.00
1	NUMBER PLATE LAMP	BROKEN	80.00	80.00
1	TAIL LAMP ASSY	MTG CRACKED	155.00	155.00
1	CVT / TRANSMISSION COVER	BROKEN	135.00	135.00
1	REFLECTOR	BROKEN / DISLODGE	180.00	180.00
1	REAR ABSORBER	DISTORTED	190.00	190.00
1	REAR RIM (ADDITIONAL)	DISTORTED	450.00	450.00
1	SWING ARM - LINKAGE RH (ADDITIONAL)	DISTORTED	275.00	275.00
1	ENGINE MOUNTING BRACKET (ADDITIONAL)	DISTORTED	220.00	220.00
	LESS 10% DISCOUNT		-185.00	-185.00
			1,665.00	1,665.00
	<u>SPECIAL NETT ITEMS</u>			
1	NUMBER PLATE (SN)	BENT	15.00	15.00
			15.00	15.00
	<u>LABOUR</u>			
	TOWING FEE.	NOT NECESSARY	40.00	-
	REMOVE & REPLACE NECESSARY PARTS, ALIGN & ETC.		250.00	150.00
	ALIGN BODY FRAME. (ADDITIONAL)		250.00	80.00
	REMOUNTING. (ADDITIONAL)		280.00	60.00
			820.00	290.00
	GRAND TOTAL		2,500.00	1,970.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,850.00

Report Ref No. CS/SMR21006229/Duf3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.