10/4/21, 12:17 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21006242/AGVF3N2

04/10/2021 Date:

REFERENCE

Reg. Date:

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1000906372

Claimant Vehicle

SMP5108C

Insured Vehicle No: EV5L

No: Date of Loss: 14/05/2021 Nature of Claim:

TP

Engine No:

Claim No: 257316

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP5108C**

Make & Model: PORSCHE PANAMERA, 3.6 PDK (A)

N/A

08/02/2011 (Man. Year: 2010) Chassis No:

WP0ZZZ97ZBL003081 Odometer: 64909 km

B03725

Colour: White 3605 cc

Engine Capacity: Market Value/New Car Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 255/45R19 Rear Tyre Size: 255/45R19 Front Left Side: Rear Left Side: Pirelli 6 mm Pirelli 6 mm Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		20,638.30	8,527.44	12,110.86	58.68
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,100.00	1,400.00	1,700.00	54.84
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	23,738.30	9,927.44	13,810.86	58.18
	Approved Total (Overridden) (S\$)		7,600.00		
	Nett Amount (S\$)	23,738.30	7,600.00	16,138.30	67.98

INSPECTION

Date of Assignment: 31/05/2021

Date Inspected: 31/05/2021 Inspected At:

10 Kaki Bukit Road 2 #03-01, First East Centre,

ADVANCE AUTO GARAGE (#03-01) (HQ)

Singapore 417868

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Oct 2021)

Parts: 144 PORSCHE PANAMERA 3.6 PDK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMP5108C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,409.50 F	*2,409.50 FL
2	1		*FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
3	1		*FRONT BUMPER SIDE HOLDER RH	Damaged	78.00 F	*78.00 FL
4	1		*FRONT BUMPER SENSOR (2 Pcs)	Damaged (1 Pc only)	625.40 F	*312.70 FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	945.00 F	*- FL
6	1		*FRONT BUMPER SPONGE	Not Necessary	320.40 F	*- FL
7	1		*FRONT BUMPER LAMP RH	Cracked	655.10 F	*655.10 FL
8	1		*FRONT BUMPER AIR GRILLE RH	Not Necessary	187.60 F	*- FL
9	1		*FRONT BUMPER NOZZLE PUMP RH	Not Necessary	445.20 F	*- FL
10	1		*HEADLAMP RH	Cracked	2,972.90 F	*2,972.90 FL
11	1		*HEADLAMP LOWER BRACKET RH	Cracked	200.40 F	*200.40 FL
12	1		*FRONT RH FENDER	Dented	1,113.20 F	*1,113.20 FL
13	1		*FRONT RH FENDER INNER SHIELD	Not Necessary	439.30 F	*- FL
14	1		*FRONT RH FENDER INNER SHIELD CLIPS	Not Necessary	50.00 F	*- FL
15	1		*FRONT RH FENDER INNER BRACKET	Bent	349.80 F	*349.80 FL
16	1		*FRONT RH LOWER ARM	Not Necessary	1,872.50 F	*- FL
17	1		*FRONT RH KNUCKLE ARM	Not Necessary	2,212.50 F	*- FL
18	1		*FRONT RH SHOCK ABSORBER	Not Necessary	1,733.60 F	*- FL
19	1		*FRONT RH WHEEL HUB C/W BEARING	Not Necessary	855.90 F	*- FL
20	1		*FRONT RH WHEEL RIM	Cut	3,122.00 FS	*1,200.00 FS
F=Fra	anchise	part. S=Spcl	Nett. L=ListItemDisc.			
				Sub Total (S\$)	20,638.30	9,341.60

 Sub Total (S\$)
 20,638.30
 9,341.60

 - List Item Discount on L Items 0.00/10.00% (S\$)
 0.00
 814.16

Total Parts (S\$) 20,638.30 8,527.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	<u>our Items</u>			
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING	New	1,000.00	500.00
3	WIRING	New	100.00	30.00
4	TO SPRAY TUFF COAT	New	120.00	30.00
5	TO PERFORM DIAGNOSTIC TEST	New	200.00	100.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
7	TO DISMANTLE FRONT UNDERCARRIAGE	New	380.00	0.00
8	TO REMOVE FRONT BUMPER SENSOR	New	150.00	60.00
		Gross Labour Cost (S\$)	3,100.00	1,400.00
	Report was un	submitted during this print-out.		

< END OF ESTIMATES >