

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21006245/ARA3Q2
Date: 09/12/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210037826	
Claimant Vehicle No :	PC8451Z	Insured Vehicle No :	SMZ2702D	
Date of Loss:	19/05/2021	Nature of Claim:	TP	Claim No: 4465737901SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC8451Z		
Make & Model:	TOYOTA HIACE, 2.8 D COMMUTER GL (A)	Engine No:	1GD8404964
Reg. Date:	22/07/2019 (Man. Year: 2019)	Chassis No:	GDH2232001650
Colour:	White	Odometer:	104346 km
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,724.26	3,755.88	2,968.38	44.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	630.00	2,370.00	79.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,724.26	4,385.88	5,338.38	54.90
Approved Total (Overridden) (S\$)		3,500.00		

(S\$)	9,724.26	3,500.00	6,224.26	64.01
+ GST 7.00/7.00% (S\$)	680.70	245.00	435.70	64.01
Nett Amount (S\$)	10,404.96	3,745.00	6,659.96	64.01
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,052.45		
Global Sum Settlement (S\$)		4,050.00		

INSPECTION

Date of Assignment: 28/05/2021

Date Inspected: 28/05/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Xin Hua Workshop Pte Ltd (HQ)
 23 Kaki Bukit Ave 4 #04-01
 Singapore 415933

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP	N/S Cracked	4,653.42 FL	*2,326.71 FL
2	2		*SETS HEADLAMP BOTTOM CLIPS (BIG)	Necessary	70.00 FL	*10.00 FL
3	1		*FRONT GRILLE	Cracked	568.90 FL	*568.90 FL
4	1		*FRONT GRILLE OUTER GARNISH (TOP)	Cracked	298.60 FL	*298.60 FL
5	1		*FRONT GRILLE OUTER GARNISH (BOTTOM)	Deformed	387.50 FL	*387.50 FL
6	1		*FRONT BUMPER	Deformed	589.60 FL	*589.60 FL
7	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	337.80 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	428.50 FL	*- FL
9	1		*FRONT BUMPER TOP SUPPORT BEAM	Dented	285.60 FL	*285.60 FL
10	1		*FRONT BUMPER LOWER GRILLE	Cracked	208.90 FL	*208.90 FL
11	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	184.00 FL	*- FL
12	1		*FRONT RADIATOR BRACE PANEL	Bent	198.70 FL	*198.70 FL
13	1		*FRONT RADIATOR AIR GUIDES	Not Necessary	291.60 FL	*- FL
14	1		*FRONT BONNET INNER LOCK	Not Necessary	235.90 FL	*- FL
15	1		*FRONT NUMBER PLATE WITH CASING	Cracked	50.00 FS	*50.00 FS
16	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
17	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*20.00 FS
18	2		*SET HEADLAMP CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,909.02	4,974.51
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,184.76	1,218.63
Total Parts (\$\$)	6,724.26	3,755.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,600.00	400.00
2	SPRAY PAINTING	New	1,200.00	200.00
3	CHECK WIRING ON HEADLAMP AND FOCUSING	New	80.00	30.00
4	ANTI RUST	New	120.00	0.00
Gross Labour Cost (S\$)			3,000.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >