

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21006252/AGA3Q2**Date:** 17/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993662
Claimant Vehicle No :	SMJ3314T	Insured Vehicle No :	SMK7858J
Date of Loss:	14/05/2021	Nature of Claim:	TP
		Claim No:	3432840691SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ3314T		
Make & Model:	MERCEDES-BENZ CLA180, 1.6 COUPE URBAN (R18 LED) (A)	Engine No:	27091031809486
Reg. Date:	28/02/2019 (Man. Year: 2018)	Chassis No:	WDD1173422N748419
Colour:	Red	Odometer:	27200 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,203.51	7,622.52	12,580.99	62.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	1,750.00	2,580.00	59.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,533.51	9,372.52	15,160.99	61.80
Approved Total (Overridden) (S\$)		7,500.00		
Nett Amount (S\$)	24,533.51	7,500.00	17,033.51	69.43
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,207.45		
Global Sum Settlement (S\$)		8,000.00		

INSPECTION

Date of Assignment:	28/05/2021	
Date Inspected:	28/05/2021	Inspected At: Kt Motorwerk (HQ) Blk 3012 Bedok Industrial Park E, #01-2020 Singapore 489978
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,526.90 FL	*1,526.90 FL
2	1		*FRONT BUMPER SIDE RETAINERS	Necessary	98.70 FL	*98.70 FL
3	1		*FRONT BUMPER SPONGE	Not Necessary	198.50 FL	*- FL
4	1		*FRONT BUMPER FOGLAMP COVER	Not Necessary	98.60 FL	*- FL
5	2		*FRONT BUMPER SENSOR	Damaged	512.60 FL	*256.30 FL
6	2		*FRONT BUMPER SENSOR HOLDER	Not Necessary	97.20 FL	*- FL
7	1		*FRONT HEADLAMP	Cut	2,780.20 FL	*2,780.20 FL
8	1		*FRONT FENDER LH	Dented	987.60 FL	*746.00 FL
9	1		*FRONT FENDER INNER SHIELD LH	Deformed	198.50 FL	*198.50 FL
10	1		*SIDE MIRROR LH ASSY	Not Necessary	896.30 FL	*- FL
11	1		*SIDE SKIRT	Repair	987.50 FL	*- FL
12	1		*FRONT LOWER ARM LH	Bent	547.30 FL	*547.30 FL
13	1		*FRONT KNUCKLE ARM LH	Damaged	835.60 FL	*835.60 FL
14	1		*FRONT WHEEL BEARING LH	Damaged	425.70 FL	*425.70 FL
15	1		*FRONT STEERING RACK	Not Necessary	2,285.90 FL	*- FL
16	1		*FRONT ANTI ROLL BAR LINK LH	Not Necessary	98.50 FL	*- FL
17	1		*FRONT ANTI ROLL BAR	Not Necessary	798.30 FL	*- FL
18	1		*FRONT DRIVE SHAFT LH	Not Necessary	1,857.00 FL	*- FL
19	1		*FRONT SPORT RIM LH	Cut	987.60 FL	*987.60 FL
20	1		*FRONT DOOR LH	Repair	2,085.90 FL	*- FL
21	1		*FRONT DOOR INNER TRIM LH	Not Necessary	725.80 FL	*- FL
22	1		*REAR DOOR LH	Not Necessary	1,986.30 FL	*- FL
23	1		*FRONT SPORT RIM LH	Not Necessary	987.40 FL	*- FL
24	1		*FRONT SPORT RIM TYRE LH	Not Necessary	280.00 FS	*- FS
25	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
26	1		*SET FRONT HEADLAMP CLIPS	Not Necessary	30.00 FS	*- FS
27	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
28	1		*SET SIDE SKIRT CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,403.90	8,462.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,200.39	840.28
Total Parts (\$\$)	20,203.51	7,622.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	600.00
2	SPRAY PAINTING	New	1,600.00	750.00
3	CHECK WIRING ON HEADLAMP AND FOCUSING	New	120.00	30.00
4	TO REMOVE AND INSTALL SENSOR	New	150.00	60.00
5	ANTI RUST	New	180.00	50.00
6	REMOVE AND INSTALL FRONT UNDERCARRIAGE	New	180.00	180.00
7	TO TRANSFER FRONT DOOR MECHANISM	New	180.00	0.00
8	TO PERFORM COMPUTERIZE WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (\$)			4,330.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >